

## ENERGY AND MINERALS DEPARTMENT OIL CONSERVATION DIVISION

March 6, 1985

TONEY ANAYA

POST OFFICE BOX 2088 STATE LAND OFFICE BUILDING SANTA FE. NEW MEXICO 87501 (505) 827-5800

HNG Oil Co. P. O. Box 2267 Midland, Texas 79702

Attention: Betty Gildon

Administrative Order TX-148

Gentlemen:

Reference is made to your request for an exception to the tubing setting requirements as contained in Division Rule 107(d)(3) for the below-named well.

Pursuant to the authority granted me by Rule 107(d)(4), you are hereby authorized to set tubing at 9375 feet in the following well:

Well Name and Number: Fate 34 Well No. 1

Location: Unit N, Sec. 34, T-23-S, R-28-E, NMPM, Eddy County, New Mexico

Remarks: Recompletion in Atoka Formation, new perforations at 11,628 to 11,635 feet and a PBTD to 11,670 feet.

The Division reserves the right to rescind this authority in the event that waste appears to be resulting therefrom.


Very truly yours,

ms

R. L. STAMETS, Division Director

RLS/MES/dr

cc: Oil Conservation Division - Artesia





P. O. BOX 2267, MIDLAND, TEXAS 79702 (915

(915) 683-4871

February 4, 1985

Oil Conservation Division P. O. Box 2088 State Land Office Bldg. Santa Fe, NM 87501

Attn: Mr. Joe D. Ramey Division Director

In Re: Fate 34, Well No. 1
Unit N, 910' FSL & 1980' FWL,
Sec. 34, T23S, R28E,
Eddy County, New Mexico

Dear Mr. Ramey:

Tubing for the above-named well has been set at 9375 feet, and casing perforated from 11,628 to 11,635 feet.

This office requests administrative exception to Rule 107d.

Very truly yours,

HNG OIL COMPANY

Betty Gildon Regulatory Analyst

enclosures

bg .





1

P. O. BOX 2267, MIDLAND, TEXAS 79702 (915) 683-4871

February 4, 1985

Oil Conservation Division P. O. Box 2088 State Land Office Bldg. Santa Fe, New Mexico 87501

Re: Fate 34, Well No. 1 Eddy County, NM

Attn: Mr. Joe D. Ramey **Division** Director

Dear Mr. Ramey:

There are several reasons why we feel that completions utilizing a TIW Polish Bore Receptable or Insert Seal Assembly is the most advantageous method to complete a well.

- The inside diameter of the seal assembly is the same as 1. the diameter of the tubing, Therefore, there is no restriction that would reduce the size of wireline tools that could be run in the hole.
- 2. The Polish Bore Receptacle has a full bore opening to the liner below it. This allows us to run bridge plugs, retainers, or bits into the liner if necessary.
- The seal assembly PBR hook-up allows for tubing movement 3. while treating the well. It will withstand higher treating pressures during stimulation than would be possible with most other production packers.
- 4. In most of the wells drilled in this area there are several zones of interest. By having the seal assembly stung into the PBR, the lowest zone can be tested and if non-productive, squeezed. The next zone of interest can then be perforated, acidized and tested. All this can be accomplished without pulling the tubing. This can save a considerable amount of time and money.

The Polish Bore Receptacle is run on the top of the liner. The Insert Seal Assembly sets in the tie back sleeve at the top of the liner.

We feel that this Packer system not only saves us a considerable amount of time and money, but also is the most reliable Packer system available. Of the several hundred wells in which HNG Oil Company has utilized this system over the past years, we have had very few failures. If you have any questions, please feel free to give me a call,

Very truly yours,

Seenge M. Hover lig

George M, Hover Petroleum Engineer III

DISTRIBUTION P. O. BOX 2088	Form C-103 Revised 10-1
SANTA FE, NEW MEXICO 87501	
U.S.O.S.	Sa. Indicate Type of Lease
OPERATOR	S. State Oll & Gus Lease No.
	×
SUNDRY NOTICES AND REPORTS ON WELLS	
USE "APPLICATION FOR PERMIT -" FORM C+1011 FOR SUCH PROPOSALS.)	7, Unit Agreement Name
Name of Operator	8. Farm or Lease Hame
NG OIL COMPANY Address of Operator	Fate 34
- 0: Box 2267, Midland, Texas 79702	1
Location of Well	10. Field and Pool, or Wildom
N 910 South 1980	South Culebra Bluff. Atoka
west 34 '23S' 28E	
THE LINE, SECTION TOWNSHIP RANGE W	~~~ ())))))))))))))))))))))))))))))))))
Milling (Control of the second s	12. County
3057.9' RDB	Eddy
Check Appropriate Box To Indicate Nature of Notice, Report or	•
NOTICE OF INTENTION TO: SUBSEQU	ENT REPORT OF:
ERFORM REMEDIAL WORK	ALTERING CASING
EMPORARILY ABANDON	PLUG AND ABANDONMENT
ULL OR ALTER CASING TEST AND CEMENT JOB	•
OTHER PB same zone	
01uta	
7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inclu work) SEE RULE 1903.	
work) SEE RULE 1903. -22-85 - Set SV Easy Drill cement retainer at 11,670'. Squeezed per with 50 sacks Class H w/.3% HR-7, .8% Halad 9, mixed at 15.	fs 11,683 to 11,768 feet
work) SEE RULE 1903. -22-85 - Set SV Easy Drill cement retainer at 11,670'. Squeezed per with 50 sacks Class H w/.3% HR-7, .8% Halad 9, mixed at 15. L-23-85 - Perforated Atoka 11,628 to 11,635 feet (8 holes, .30")	fs 11,683 to 11,768 feet
work) SEE RULE 1903. -22-85 - Set SV Easy Drill cement retainer at 11,670'. Squeezed per with 50 sacks Class H w/.3% HR-7, .8% Halad 9, mixed at 15.	fs 11,683 to 11,768 feet
<pre>work) SEE RULE 1903. 22-85 - Set SV Easy Drill cement retainer at 11,670'. Squeezed per with 50 sacks Class H w/.3% HR-7, .8% Halad 9, mixed at 15. L-23-85 - Perforated Atoka 11,628 to 11,635 feet (8 holes, .30") L-25-85 - Acidized w/3500 gals 7-1/2% Morrow flo BC acid.</pre>	fs 11,683 to 11,768 feet 8 ppg.
<ul> <li>work) SEE RULE 193.</li> <li>-22-85 - Set SV Easy Drill cement retainer at 11,670'. Squeezed perwith 50 sacks Class H w/.3% HR-7, .8% Halad 9, mixed at 15.</li> <li>1-23-85 - Perforated Atoka 11,628 to 11,635 feet (8 holes, .30")</li> <li>1-25-85 - Acidized w/3500 gals 7-1/2% Morrow flo BC acid.</li> <li>1-30-85 - Opened to sales line, FTP 300, CP 1800, Flow rate of 190 Mc</li> </ul>	fs 11,683 to 11,768 feet 8 ppg.
<pre>work) SEE RULE 1903. 22-85 - Set SV Easy Drill cement retainer at 11,670'. Squeezed per with 50 sacks Class H w/.3% HR-7, .8% Halad 9, mixed at 15. L-23-85 - Perforated Atoka 11,628 to 11,635 feet (8 holes, .30") L-25-85 - Acidized w/3500 gals 7-1/2% Morrow flo BC acid.</pre>	fs 11,683 to 11,768 feet 8 ppg.
<ul> <li>work) SEE RULE 193.</li> <li>-22-85 - Set SV Easy Drill cement retainer at 11,670'. Squeezed perwith 50 sacks Class H w/.3% HR-7, .8% Halad 9, mixed at 15.</li> <li>1-23-85 - Perforated Atoka 11,628 to 11,635 feet (8 holes, .30")</li> <li>1-25-85 - Acidized w/3500 gals 7-1/2% Morrow flo BC acid.</li> <li>1-30-85 - Opened to sales line, FTP 300, CP 1800, Flow rate of 190 Mc</li> </ul>	fs 11,683 to 11,768 feet 8 ppg.
<ul> <li>work) SEE RULE 193.</li> <li>-22-85 - Set SV Easy Drill cement retainer at 11,670'. Squeezed perwith 50 sacks Class H w/.3% HR-7, .8% Halad 9, mixed at 15.</li> <li>1-23-85 - Perforated Atoka 11,628 to 11,635 feet (8 holes, .30")</li> <li>1-25-85 - Acidized w/3500 gals 7-1/2% Morrow flo BC acid.</li> <li>1-30-85 - Opened to sales line, FTP 300, CP 1800, Flow rate of 190 Mc</li> </ul>	fs 11,683 to 11,768 feet 8 ppg.
<ul> <li>work) SEE RULE 193.</li> <li>-22-85 - Set SV Easy Drill cement retainer at 11,670'. Squeezed perwith 50 sacks Class H w/.3% HR-7, .8% Halad 9, mixed at 15.</li> <li>1-23-85 - Perforated Atoka 11,628 to 11,635 feet (8 holes, .30")</li> <li>1-25-85 - Acidized w/3500 gals 7-1/2% Morrow flo BC acid.</li> <li>1-30-85 - Opened to sales line, FTP 300, CP 1800, Flow rate of 190 Mc</li> </ul>	fs 11,683 to 11,768 feet 8 ppg.
<ul> <li>work) SEE RULE 193.</li> <li>-22-85 - Set SV Easy Drill cement retainer at 11,670'. Squeezed perwith 50 sacks Class H w/.3% HR-7, .8% Halad 9, mixed at 15.</li> <li>1-23-85 - Perforated Atoka 11,628 to 11,635 feet (8 holes, .30")</li> <li>1-25-85 - Acidized w/3500 gals 7-1/2% Morrow flo BC acid.</li> <li>1-30-85 - Opened to sales line, FTP 300, CP 1800, Flow rate of 190 Mc</li> </ul>	fs 11,683 to 11,768 feet 8 ppg.
<ul> <li>work) SEE RULE 193.</li> <li>-22-85 - Set SV Easy Drill cement retainer at 11,670'. Squeezed perwith 50 sacks Class H w/.3% HR-7, .8% Halad 9, mixed at 15.</li> <li>1-23-85 - Perforated Atoka 11,628 to 11,635 feet (8 holes, .30")</li> <li>1-25-85 - Acidized w/3500 gals 7-1/2% Morrow flo BC acid.</li> <li>1-30-85 - Opened to sales line, FTP 300, CP 1800, Flow rate of 190 Mc</li> </ul>	fs 11,683 to 11,768 feet 8 ppg.
<ul> <li>work) SEE RULE 193.</li> <li>-22-85 - Set SV Easy Drill cement retainer at 11,670'. Squeezed perwith 50 sacks Class H w/.3% HR-7, .8% Halad 9, mixed at 15.</li> <li>1-23-85 - Perforated Atoka 11,628 to 11,635 feet (8 holes, .30")</li> <li>1-25-85 - Acidized w/3500 gals 7-1/2% Morrow flo BC acid.</li> <li>1-30-85 - Opened to sales line, FTP 300, CP 1800, Flow rate of 190 Mc</li> </ul>	fs 11,683 to 11,768 feet 8 ppg.
<ul> <li>work) SEE AULE 1933.</li> <li>-22-85 - Set SV Easy Drill cement retainer at 11,670'. Squeezed perwith 50 sacks Class H w/.3% HR-7, .8% Halad 9, mixed at 15.4</li> <li>1-23-85 - Perforated Atoka 11,628 to 11,635 feet (8 holes, .30")</li> <li>1-25-85 - Acidized w/3500 gals 7-1/2% Morrow flo BC acid.</li> <li>1-30-85 - Opened to sales line, FTP 300, CP 1800, Flow rate of 190 Mc PBTD 11,670'. 2-7/8" tubing with PBR at 9375 feet.</li> </ul>	fs 11,683 to 11,768 feet 8 ppg.
<ul> <li>work) SEE RULE 193.</li> <li>-22-85 - Set SV Easy Drill cement retainer at 11,670'. Squeezed perwith 50 sacks Class H w/.3% HR-7, .8% Halad 9, mixed at 15.</li> <li>1-23-85 - Perforated Atoka 11,628 to 11,635 feet (8 holes, .30")</li> <li>1-25-85 - Acidized w/3500 gals 7-1/2% Morrow flo BC acid.</li> <li>1-30-85 - Opened to sales line, FTP 300, CP 1800, Flow rate of 190 Mc</li> </ul>	fs 11,683 to 11,768 feet 8 ppg.
<ul> <li>worky SEE AULE 1903.</li> <li>22-85 - Set SV Easy Drill cement retainer at 11,670'. Squeezed perwith 50 sacks Class H w/.3% HR-7, .8% Halad 9, mixed at 15.1</li> <li>1-23-85 - Perforated Atoka 11,628 to 11,635 feet (8 holes, .30")</li> <li>1-25-85 - Acidized w/3500 gals 7-1/2% Morrow flo BC acid.</li> <li>1-30-85 - Opened to sales line, FTP 300, CP 1800, Flow rate of 190 Mc PBTD 11,670'. 2-7/8" tubing with PBR at 9375 feet.</li> </ul>	fs 11,683 to 11,768 feet 8 ppg. f/day, 0 cond., 0 water.
<ul> <li>work) SEE AULE 1933.</li> <li>-22-85 - Set SV Easy Drill cement retainer at 11,670'. Squeezed perwith 50 sacks Class H w/.3% HR-7, .8% Halad 9, mixed at 15.4</li> <li>1-23-85 - Perforated Atoka 11,628 to 11,635 feet (8 holes, .30")</li> <li>1-25-85 - Acidized w/3500 gals 7-1/2% Morrow flo BC acid.</li> <li>1-30-85 - Opened to sales line, FTP 300, CP 1800, Flow rate of 190 Mc PBTD 11,670'. 2-7/8" tubing with PBR at 9375 feet.</li> </ul>	fs 11,683 to 11,768 feet 8 ppg.
<ul> <li>worky SEE AULE 1903.</li> <li>22-85 - Set SV Easy Drill cement retainer at 11,670'. Squeezed perwith 50 sacks Class H w/.3% HR-7, .8% Halad 9, mixed at 15.1</li> <li>1-23-85 - Perforated Atoka 11,628 to 11,635 feet (8 holes, .30")</li> <li>1-25-85 - Acidized w/3500 gals 7-1/2% Morrow flo BC acid.</li> <li>1-30-85 - Opened to sales line, FTP 300, CP 1800, Flow rate of 190 Mc PBTD 11,670'. 2-7/8" tubing with PBR at 9375 feet.</li> </ul>	fs 11,683 to 11,768 feet 8 ppg. f/day, 0 cond., 0 water.
<ul> <li>worky SEE AULE 1903.</li> <li>22-85 - Set SV Easy Drill cement retainer at 11,670'. Squeezed perwith 50 sacks Class H w/.3% HR-7, .8% Halad 9, mixed at 15.1</li> <li>1-23-85 - Perforated Atoka 11,628 to 11,635 feet (8 holes, .30")</li> <li>1-25-85 - Acidized w/3500 gals 7-1/2% Morrow flo BC acid.</li> <li>1-30-85 - Opened to sales line, FTP 300, CP 1800, Flow rate of 190 Mc PBTD 11,670'. 2-7/8" tubing with PBR at 9375 feet.</li> </ul>	fs 11,683 to 11,768 feet 8 ppg. f/day, 0 cond., 0 water.
<ul> <li>worky SEE AULE 1903.</li> <li>22-85 - Set SV Easy Drill cement retainer at 11,670'. Squeezed perwith 50 sacks Class H w/.3% HR-7, .8% Halad 9, mixed at 15.1</li> <li>1-23-85 - Perforated Atoka 11,628 to 11,635 feet (8 holes, .30")</li> <li>1-25-85 - Acidized w/3500 gals 7-1/2% Morrow flo BC acid.</li> <li>1-30-85 - Opened to sales line, FTP 300, CP 1800, Flow rate of 190 Mc PBTD 11,670'. 2-7/8" tubing with PBR at 9375 feet.</li> </ul>	fs 11,683 to 11,768 feet 8 ppg. f/day, 0 cond., 0 water.
<ul> <li>worky ster NULE 1951.</li> <li>22-85 - Set SV Easy Drill cement retainer at 11,670'. Squeezed perwith 50 sacks Class H w/.3% HR-7, .8% Halad 9, mixed at 15.4</li> <li>L-23-85 - Perforated Atoka 11,628 to 11,635 feet (8 holes, .30")</li> <li>L-25-85 - Acidized w/3500 gals 7-1/2% Morrow flo BC acid.</li> <li>L-30-85 - Opened to sales line, FTP 300, CP 1800, Flow rate of 190 Mc PBTD 11,670'. 2-7/8" tubing with PBR at 9375 feet.</li> <li>A. I hereby century that the momentation above is true and complete to the best of me knowledge and belief.</li> <li>A. I hereby century that the momentation above is true and complete to the best of me knowledge and belief.</li> <li>A. I hereby century that the momentation above is true and complete to the best of me knowledge and belief.</li> <li>A. I hereby century that the momentation above is true and complete to the best of me knowledge and belief.</li> <li>A. I hereby century that the momentation above is true and complete to the best of me knowledge and belief.</li> <li>A. I hereby century that the momentation above is true and complete to the best of me knowledge and belief.</li> <li>A. I hereby century that the momentation above is true and complete to the best of me knowledge and belief.</li> <li>A. I hereby century that the momentation above is true and complete to the best of me knowledge and belief.</li> <li>A. I hereby century that the momentation above is true and complete to the best of me knowledge and belief.</li> <li>A. I hereby century that the momentation above is true and complete to the best of me knowledge and belief.</li> </ul>	fs 11,683 to 11,768 feet 8 ppg. f/day, 0 cond., 0 water.