

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company ConocoPhillips Company	Contact Kenneth N. Andersen
Address 4001 Penbrook, Odessa, TX 79762-5917	Telephone No. 505.391.3158
Facility Name MCA Unit Battery # 2	Facility Type Oil and Gas

Surface Owner BLM	Mineral Owner BLM	Lease No LC - 057210
--------------------------	--------------------------	-----------------------------

LOCATION OF RELEASE

Unit Letter D	Section 28	Township 17S	Range 32E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea Co.
-------------------------	----------------------	------------------------	---------------------	---------------	------------------	---------------	----------------	--------------------------

Latitude **32.81194N** Longitude **-103.77518W**

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 23 bbl (0 oil, 23 water)	Volume Recovered (0 oil, 0 water)
Source of Release MCA Unit Battery # 2 4" produced water trunk line.	Date and Hour of Occurrence 07/06/2006 0530hrs	Date and Hour of Discovery 07/06/2006 0945hrs
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* A dresser sleeve failed due to corrosion, age, & fatigue on the produced water trunk line. The site will be delineated & a remediation plan will be submitted to the NMOCD for approval.		
Describe Area Affected and Cleanup Action Taken.* 100'X15' & 755'X3.5' of damp sandy pasture with no fluid recovered. However a vacuum truck was used to empty the 4" trunk line. The dresser sleeve was replaced with a flanged fiberglass spool.		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Kenneth N. Andersen</i>	OIL CONSERVATION DIVISION	
Printed Name: Kenneth N. Andersen	Approved by District Supervisor:	
Title: HSER PSM Lead	Approval Date:	Expiration Date:
E-mail Address: ken.n.andersen@conocophillips.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 07/08/2006 Phone: 505.391.3158		

- Attach Additional Sheets If Necessary

Facility - PAC0619939966
Incident - PAC0619940049
application - PAC0619940284

RP#959