

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

## Release Notification and Corrective Action

## OPERATOR

☒ Initial Report☐ Final Report

Name of Company <i>LATIGO Petroleum, INC</i>	Contact <i>PATRICK ELLIS</i>
Address <i>P.O. Box 10340 Midland, Texas 79702</i>	Telephone No. <i>432 685-8148</i>
Facility Name <i>EVA E Blinby Federal # 1</i>	Facility Type <i>Well - injection transfer line</i>

Surface Owner	Mineral Owner	Lease No. <i>NMLE-064-118</i>
---------------	---------------	-------------------------------

LOCATION OF RELEASE *30 02S/0936 0000*

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
<i>E</i>	<i>34</i>	<i>23S</i>	<i>37E</i>	<i>1980</i>	<i>FSL</i>	<i>660</i>	<i>FEL</i>	<i>Lea</i>

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

## NATURE OF RELEASE

Type of Release <i>Produced Water</i>	Volume of Release <i>150 BBLs</i>	Volume Recovered <i>135 BBLs</i>
Source of Release <i>TRANSFER LINE</i>	Date and Hour of Occurrence	Date and Hour of Discovery <i>4-8-07</i>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <i>4-8-07 Left voice message with OCD + BLM.</i>	
By Whom? <i>FRANK UNDERWOOD</i>	Date and Hour <i>7:00pm 4-8-07</i>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

*N/A*

Describe Cause of Problem and Remedial Action Taken.\*

*Produced water transfer line was ruptured when plugging unit ran over line. Transfer line originated from G.H. MATTIX injection station.*

Describe Area Affected and Cleanup Action Taken.\*

*All free fluid was picked up. Highlander Environmental was contacted to evaluate spill area. Will send remediation plans for approval after evaluations.*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

## OIL CONSERVATION DIVISION

Signature: *Patrick L. Ellis*Printed Name: *PATRICK L. ELLIS*Title: *EHS Supervisor*E-mail Address: *ellispl@pogoproducing.com*Date: *4-26-07*Phone: *(432) 685-8148*Approved by District Supervisor: *[Signature]*Approval Date: *6-27-07*Expiration Date: *8-27-07*

Conditions of Approval:

Attached ☐

FINAL DUE BY

\* Attach Additional Sheets If Necessary

*RP#1443*