

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

☒ Initial Report ☐ Final Report

Name of Company Plains Pipeline	Contact Camille Reynolds
Address 3112 W. US Hwy 82, Lovington, NM 88260	Telephone No. 505-441-0965
Facility Name Vacuum Sour 4 Inch Trap	Facility Type 4" Steel Pipeline

Surface Owner SLO	Mineral Owner	Lease No.
-------------------	---------------	-----------

**LOCATION OF RELEASE**

Unit Letter J	Section 33	Township 17S	Range 35E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	---------------

Latitude 32° 47' 17.3" Longitude 103° 27' 33.9"

**NATURE OF RELEASE**

Type of Release Crude Oil	Volume of Release 30 barrels	Volume Recovered 0 barrels
Source of Release 4" Steel Pipeline	Date and Hour of Occurrence 07/20/2007 @ 13:00	Date and Hour of Discovery 07/20/2007 @ 13:30
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Pat Richards	
By Whom? Camille Reynolds	Date and Hour 07/20/2007 @ 15:45	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken: Tie in valve on the Phillips Central 8 inch line malfunctioned allowing oil to flow back into the idled 4 inch receiver trap. Internal corrosion on the idled 4 inch line resulted in the crude oil release. The line was cut and capped. Line idled, therefore, pressure and volume is not applicable.

Describe Area Affected and Cleanup Action Taken.\* The initial visual impacted area was approximately 80 feet long by 20 feet wide. The impacted soil is being stockpiled on site on a 6-mil poly liner.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Camille Reynolds</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Camille Reynolds	Approved by District Supervisor <i>[Signature]</i>	
Title: Remediation Coordinator	Approval Date: <u>7.26.07</u>	Expiration Date: <u>9.28.07</u>
E-mail Address: <u>cjreynolds@paalp.com</u>	Conditions of Approval: <u>Submit Final C-141</u>	Attached <input type="checkbox"/>
Date: <u>07/26/2007</u>	Phone: <u>505-441-0965</u>	

\* Attach Additional Sheets If Necessary

W/ ATTACHMENTS BY

RP#1501