



STATE OF NEW MEXICO  
ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT  
OIL CONSERVATION DIVISION

GARREY CARRUTHERS  
GOVERNOR

POST OFFICE BOX 2088  
STATE LAND OFFICE BUILDING  
SANTA FE, NEW MEXICO 87504  
(505) 827-5800

August 23, 1990

Meridian Oil, Inc.  
P.O. Box 4289  
Farmington, NM 87499-4289

Attention: Peggy Bradfield

*RE: Unorthodox coal gas well location, Huerfanito Unit Well No. 38,  
1150' FS - 1520' FEL (Unit O); 28-T27N-R9W, NMPM, Basin-  
Fruitland Coal Gas Pool, San Juan County, New Mexico.*

Dear Ms. Bradfield:

Having received several applications in the past to recompleat existing wells to the Basin-Fruitland Coal Gas Pool at unorthodox coal gas well locations, usually Pictured Cliffs wells, which are off pattern for coal gas development, it appears that additional information may be necessary to properly evaluate future filings in instances when there are two wells in the proposed coal spacing unit producing from the same formation in which the one to be recompleated is also off-pattern.

In the immediate instance, the proposed E/2 320-acre coal dedication has two Ballard Pictured Cliffs Gas wells; the Huerfanito Unit Well No. 41 located in Unit B and the Huerfanito Unit Well No. 38 located in Unit O. Why was the No. 38 chosen over the No. 41 well? Also, how does this off-pattern recompleat effect coal development in the immediate area? Please submit any supporting production data, engineering evaluation and related technical data to support your choice of wells for recompleat. Also submit a plat of the offsetting sections showing the coal completions presently planned or currently producing and provide a discussion addressing the proposed off-pattern development.

Should you have any questions, please contact me.

Sincerely,

Michael E. Stogner  
Chief Hearing Officer/Engineer

cc: Oil Conservation Division - Aztec  
US Bureau of Land Management - Farmington