

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation District
1220 South St. Francis Dr.
Santa Fe, NM 87505

JAN - 8 2008
OCD-ARTESIA

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report



Name of Company DCP Midstream, LP		Contact Randall K. Counts
Address P O. Box 50020, Midland, 79710		Telephone No. (915) 677-5214
Facility Name Burton Flats Booster		Facility Type Compressor Station
Surface Owner	Mineral Owner	Lease No.

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line North	Feet from the	East/West Line East	County Eddy
-------------	---------	----------	-------	---------------	---------------------------	---------------	------------------------	----------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Air	Volume of Release 491.00 mcf/event	Volume Recovered 0.00 mcf/event
Source of Release Emergency Blowdown Vent	Date and Hour of Release 12/28/2007 7:00 AM	Date and Hour of Discovery 12/28/2007 7:00 AM
Was Immediate Notice Given? <input type="radio"/> Yes <input checked="" type="radio"/> No <input type="radio"/> Not Required	If YES, to Whom? Don Shainin	
By Whom? Mary B. Matthews	Date and Hour 12/31/2007 10:54 AM	
Was a Watercourse Reached? <input type="radio"/> Yes <input checked="" type="radio"/> No	If YES, Volume Impacting the Watercourse 0 00 mcf/event	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* Burton Flats Booster Station Units No. 1, 2, 3, 4, 5, 6 & 7 were shut down so construction could make new 12" pipeline tie ins to install a new pig launcher.		
Describe Area Affected and Cleanup Action Taken.* DCP dispatched a Field Operator to aid in shutting the booster station down. Once the tie-ins were complete, the Field Operator restarted the all units and the site was returned to normal.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Johnnie Bradford	Approved By District Supervisor: 	
Title: FS-Sr Env Eng/Spec	Approval Date: JAN 09 2008	Expiration Date:
E-mail Address: JBRADFORD@dcpmidstream.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 01/03/2008 3:01 PM. Phone: () -		

* Attach additional sheets if necessary