<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> 1301 W. Grand Avenue, Artesia, NM 88210 <u>District III</u> 1000 Rio Brazos Road, Aztec, NM 87410 <u>District IV</u>

State of New Mexico Energy Minerals and Natural Resources

> **Oil Conservation Division** 1220 South St. Francis Dr.

Form C-141 Revised October 10, 2003 Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back

-

.

Rule	110	on	Dack
	side	of	form

٦,٠.

.

Release Notification and Corrective Action OPERATOR x Initial Report Final Report ame of Company Plains Pipeline, LP Contact Camille Reynolds kfress 3112 West US Hvy 82, Lovington, NM 88260 Telephone No. 50:-411-0965 cility Name Ramsey "C" 4 and 6 Inch Facility Type 6"Steel Pipeline rface Owner Legacy Reserve Mineral Owner Lease No. LOCATION OF RELEASE Longitude J03" 06'-41.8" nit Leter Section Township Range Yest Of S. 7" Longitude J03" 06'-41.8" NATURE OF RELEASE NATURE OF RELEASE po f Release Crude Oil Volume of Release 20 barcits Volume Recovered 1 barcel uree of Release 6 Steel Pipeline Data and Hour of Occurrence Data and Hour Of Discovery Div/A2008 & 11:30 Data and Hour Of Discovers Data and Hour Of Discovers Whom? Yes No No Nature Reprodes as a Watercourse Reached? Yes No If YES, Volume Impacting the Watercourse RECEIVED awa dutercourse was Impacted, Describe Fully.* JAN 1 5 2008 seriebe Cause of Problem and Remedial Action Taken.* The impacted soil was excurated and stockpiled on plastic. Aerial extent of surface impact was proximat	220 S. St. Francis Dr., Santa Fe, NM 87505	Santa Fe	e, NM 875			side of form		
OPERATOR x Initial Report Final Report Iddees Contact Camille Reynolds Iddees Iddees<	Release				ction			
anne of Company Plains Pipeline, LP Contact Camille Reynolds idress 3112 West US Hwy 82, Lavington, NM 88260 Telephone No. 505-441-0965 cillity Name Ramsey "C" 4 and 6 Inch Facility Type 6"Steel Pipeline rface Owner Legacy Reserve Mineral Owner LOCATION OF RELEASE Lease No. it Letter Section 24 757 Longitude 103° 06' 41.8" Lutitude, 32° 06' 45.7" Longitude Latitude, 32° 06' 45.7" Longitude Lotitude of Release 7 Steel Pipeline Date and Hour of Occurrence Date and Hour Of Occurrence Date and Hour of Occurrence Volume Research Date and Hour Of Occurrence UMOm? Camille Reynolds Date and Hour Of Occurrence watercourse Reached? Yes Yes No No Not Required If YES, To Whon? TY S. Steel Pipeline JAN 1 5 2008 HOM2008/gl 14:25 Whom? Camille Reynolds Steel Steel Pipeline Steeles: Oblight Pipeline JAN 1 5 2008 HOM2008/gl 14:25 JAN 1 5 2008 HOM2008/gl 14:25 sective Cause of Problem and Remedial Action Taken.* The impacted soil was exeavat						al Report 🗍 Final Repor		
Iddress 3112 West US Hwy 82, Lovington, NM 88260 Telephone No. 505-441-0965 cility Name Ransey "C" 4 and 6 Inch Facility Type 6"Steel Pipeline rike Owner Legacy Reserve Mineral Owner LocA TION OF RELEASE Lease No. it Letter Section Township 24 25S 37E Feet from the North/South Line Feet from the County Lastitude_ 32° 06' 45.7" Longitude_ 103° 06' 41.8" Nature of Release 20 barrels Volume Recovered 1 harel pe of Release Crude Oil Volume Recovered 1 harel Date and Hour of Occurrence Date and Hour of Occurrence Date and Hour of Occurrence pas Immediate Notice Given? Yes No Not Required If YES, To Whom? NA Watercourse Reached? a Watercourse was Impacted, Describe Fully.* JAN 1 5 2008 service Case of Problem and Remedial Action Taken.* During purging activities discovered leak in the 6 inch pipeline strates overtaice impact was proximately 6,500 square feet. Autercourse was Impacted, Describe Fully.* service A Affected and Cleanup Action Taken.* The impacted soil was excavated and stockpiled on plastic. Actrial extent of surface impact was proximately 6,500 square feet. eredy certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and platie	Jame of Company Plains Pipeline, LP							
rface Owner Legacy Reserve Mineral Owner Later Covered Legacy Reserve LocATION OF RELEASE it Letter Section Township Range Feet from the North/South Line Peet from the Section Latitude 32° 06'45.7" Longitude 103° 06'41.8" NATURE OF RELEASE Volume Recovered 1 barrel Pe of Release Crude OII Volume of Release 20 barrels Police of Release 6'' Steel Pipeline Date and Hour of Occurrence Date and Hour of Occurrence Date and Hour of Obscovery 0104/2008 (11:30) 0104/2008 (01:1-25 as immediate Notice Given? Yes Whom? Par Richards Whom? Particle 11:25 To Whom? Particle 11:25 No Internet Hour of UM/2008 (01:4:25 If YES, Volume Impacting the Waterourse ReceletVED A Waterourse was Impacted, Describe Fuilty.* JAN 1 5 2008 Here Cause of Problem and Remedial Action Taken.* During purging activities discovered leak in the 6 inch pipeline Science of Science is unavailable. Sectibe Cause of Problem and Remedial Action Taken.* The impacted soil was excavated and stockpiled on plastic. Aerial extent of surface impact was proximately 6.500 square feet. eredy certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and plations and perform corrective actions for releases which								
LOCATION OF RELEASE LOCATION OF RELEASE ift Letter Section Township Range Feet from the North/South Line Feet from the East/West Line County Latitude_32*06*45.7* Longitude_103*06*14.8* NATURE OF RELEASE pe of Release Crude Oil Volume of Release 20 barels Volume of Release 20 barels Volume of Release 20 barels as Immediate Notice Given? Yes Not Required DitAutor 00 Courrence Date and Hour of Occurrence 0104/2008 @ 11.30 U/04/2008 @ 11.45 If YES, Volume Impacting the Watercourse RECEIVED as a Watercourse Reached? Yes No Not Required as a Watercourse was Impacted, Describe Fully.* JAN 1 5 2008 asoribe Cause of Problem and Remedial Action Taken.* During purging activities discovered leak in the 6 inch pipelinit esoting methade on prostor is unavailable. scribe Area Affected and Cleanup Action Taken.* The impacted soil was excavated and stockpiled on plastic. Acrial extent of surface impact was proximately 6,500 square feet. eredy certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and plating and over of inability for companiance with any endanger blie health or the revionment. The acegonace of a C-141 report by the NMOCD maked as Tinal Report does not releave								
LOCATION OF RELEASE LOCATION OF RELEASE ift Letter Section Township Range Feet from the North/South Line Feet from the East/West Line County Latitude_32*06*45.7* Longitude_103*06*14.8* NATURE OF RELEASE pe of Release Crude Oil Volume of Release 20 barels Volume of Release 20 barels Volume of Release 20 barels as Immediate Notice Given? Yes Not Required DitAutor 00 Courrence Date and Hour of Occurrence 0104/2008 @ 11.30 U/04/2008 @ 11.45 If YES, Volume Impacting the Watercourse RECEIVED as a Watercourse Reached? Yes No Not Required as a Watercourse was Impacted, Describe Fully.* JAN 1 5 2008 asoribe Cause of Problem and Remedial Action Taken.* During purging activities discovered leak in the 6 inch pipelinit esoting methade on prostor is unavailable. scribe Area Affected and Cleanup Action Taken.* The impacted soil was excavated and stockpiled on plastic. Acrial extent of surface impact was proximately 6,500 square feet. eredy certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and plating and over of inability for companiance with any endanger blie health or the revionment. The acegonace of a C-141 report by the NMOCD maked as Tinal Report does not releave	urface Owner Legacy Reserve	Mineral Owner			Lease N	lo.		
it Letter Section Township Range Section the North/South Line Feet from the East/West Line County Latirude_32*06*45.7* Longitude_103*06*41.8* NATURE OF RELEASE pe of Release Crude Oil Volume of Release 20 barels Volume release Volume release urce of Release Crude Oil Date and Hour of Ocaurence Date and Hour of Ocaurence 0104/2008 (a) 11-35 as Immediate Notice Given? Yes Not Not Required Pate and Hour of Ocaurence 0104/2008 (a) 11-35 Whom? Camille Reynolds as a Watercourse Reached? If YES, Volume Impacting the Watercourse RECEIVED a Watercourse was Impacted, Describe Fully.* JAN 1 5 2008 scribe Area Affected and Cleanup Action Taken.* During purging activities discovered leak in the 6 inch pipelinic Boding methes overacted or information concerning volume and pressure is unavailable. scribe Area Affected and Cleanup Action Taken.* The impacted soil was excavated and stockpiled on plastic. Aerial extent of surface impact was proximately 6,500 square feet. eredy certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and remediate commination that pase a threat to ground water, surface water, human health the environment. The acceptance of a C-141 report by the NMOCD maked as Tinal Report does not relieve the operator of inability for		Ň						
I 24 258 37E Lea Latitude 32° 06'45.7" Longitude 103° 06'41.8" NATURE OF RELEASE Pe of Release Crude OII Date and Hour of Occurrence Date and Hour of Occurrence Date and Hour of Occurrence OI/04/2008 @ 11:25 as Immediate Notice Given? Whon? Yes No Not Required National Hour of 0/04/2008@ 14:25 If YES, Volume Impacting the Watercourse RECEIVED A Watercourse Reached? JAN 1 5 2008 Bate and Hour of 0/04/2008@ 14:25 If YES, Volume Impacting the Watercourse RECEIVED A Watercourse was Impacted, Describe Fully.* JAN 1 5 2008 Bate and Hour of 0/04/2008@ 14:25 If YES, Volume Impacting wolume and pressure is unavailable. Secribe Cause of Problem and Remedial Action Taken.* During purging activities discovered leak in the 6 inch pipeline Posities the of surface impact was proximately 6,500 square feet. Secribe Area Affected and Cleanup Action Taken.* The impacted soil was exeavated and stockpiled on plastic.	nit Letter Section Township Range Feet f				Fast/West Line	County		
Lantruce 02.06.41.5 NATURE OF RELEASE NATURE OF RELEASE Point of Release Crude OII Volume Of Release 20 barrels Volume Of Release 20 barrels Date and Hour of Occurrence Date and Hour of Discovery OI/04/2008 @ 11.45 as Immediate Notice Given? Whom? Camille Reynolds Date and Hour OI/04/2008 @ 11.45 as a Watercourse Reached? Whom? Camille Reynolds Date and Hour OI/04/2008 @ 11.45 as a Watercourse Reached? Whom? Camille Reynolds Date and Hour OI/04/2008 @ 11.45 as a Watercourse was Impacted, Describe Fully.* JAN 1 5 2008 Bescribe Cause of Problem and Remedial Action Taken.* During purging activities discovered leak in the 6 inch pipeline was installed on the line to mitigate the release. The line is idle so information concerning volume and pressure is unavailable. secribe Cause of Problem and Remedial Action Taken.* The impacted soil was excavated and stockpiled on plastic. Aerial extent of surface impact was proximately 6,500 square feet. Secribe Area Affected and Cleanup Action Taken.* The impacted soil was excavated and stockpiled on plastic. Aerial extent of surface which may endanger floc head to repo			South Enite	i oot nom me	Bust West Enite			
Lantruce 02.06.41.5 NATURE OF RELEASE NATURE OF RELEASE Point of Release Crude OII Volume Of Release 20 barrels Volume Of Release 20 barrels Date and Hour of Occurrence Date and Hour of Discovery OI/04/2008 @ 11.45 as Immediate Notice Given? Whom? Camille Reynolds Date and Hour OI/04/2008 @ 11.45 as a Watercourse Reached? Whom? Camille Reynolds Date and Hour OI/04/2008 @ 11.45 as a Watercourse Reached? Whom? Camille Reynolds Date and Hour OI/04/2008 @ 11.45 as a Watercourse was Impacted, Describe Fully.* JAN 1 5 2008 Bescribe Cause of Problem and Remedial Action Taken.* During purging activities discovered leak in the 6 inch pipeline was installed on the line to mitigate the release. The line is idle so information concerning volume and pressure is unavailable. secribe Cause of Problem and Remedial Action Taken.* The impacted soil was excavated and stockpiled on plastic. Aerial extent of surface impact was proximately 6,500 square feet. Secribe Area Affected and Cleanup Action Taken.* The impacted soil was excavated and stockpiled on plastic. Aerial extent of surface which may endanger floc head to repo				1				
pe of Release Crude Oil Volume of Release 20 barrêls Volume Recovered 1 barrel Date and Hour of Occurrence Date and Hour of Discovery Date and Hour of Discovery as Immediate Notice Given? Yes No Not Required Park Cichards as a Watercourse Reached? Yes No Not Required Park Cichards as a Watercourse Reached? Yes No Date and Hour 01/04/2008@14:25 If YES, To Whom? Park Cichards Date and Hour 01/04/2008@14:25 as a Watercourse Reached? Yes No a Watercourse was Impacted, Describe Fully.* JAN 1.5 2008 scribe Cause of Problem and Remedial Action Taken.* During purging activities discovered leak in the 6 inch pipeline Restores of Problem and Remedial Action Taken.* The impacted soil was excavated and stockpiled on plastic. Aerial extent of surface impact was proximately 6,500 square feet. seribe Area Affected and Cleanup Action Taken.* The impacted soil was excavated and stockpiled on plastic. Aerial extent of surface impact was proximately 6,500 square feet. ereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and plation sall operators are required to report and/or file certain release notifications and perform correcuive actions for releases which may endanger blic health or the environment. The acceptance of a C-141 report by the MNOCD marked as "Final Report" does not reli	Latitude_32°06'45.7"	, 	Longitude	<u>103° 06' 41.8"</u>	· · · ·	-		
pe of Release Crude Oil Volume of Release 20 barcêls Volume Recovered 1 barrel Date and Hour of Occurrence Date and Hour of Discovery Ol/04/2008 @ 11:30 as Immediate Notice Given? Yes No Not Required Part Richards Whom? Camille Reynolds Date and Hour 01/04/2008 @ 11:45 If YES, To Whom? Part Richards as a Watercourse Reached? Yes No Date and Hour 01/04/2008 @ 14:25 If YES, Volume Impacting the Watercourse Date and Hour 01/04/2008 @ 14:25 as a Watercourse Reached? Yes No Date and Hour 01/04/2008 @ 14:25 If YES, Volume Impacting the Watercourse Date and Hour 01/04/2008 @ 14:25 as a Watercourse was Impacted, Describe Fully.* JAN 1 5 2008 JAN 1 5 2008 scribe Cause of Problem and Remedial Action Taken.* During purging activities discovered leak in the 6 inch pipeline Restore of ordeore cause of Problem and Remedial Action Taken.* The impacted soil was excavated and stockpiled on plastic. Aerial extent of surface impact was proximately 6,500 square feet. seribe Area Affected and Cleanup Action Taken.* The impacted soil was excavated and stockpiled on plastic. Aerial extent of surface impact was proximately 6,500 square feet. ereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and plation on trelieve the operator of responsibility for compliance with any endanger		NATURE	OF RELI	EASE				
as Immediate Notice Given? 01/04/2008 @ 11:30 01/04/2008 @ 11:45 if YES, To Whom? If YES, To Whom? If YES, To Whom? as a Matercourse Reached? If YES, To Whom? If YES, Yolume Impacting the Watercourse RECEIVED as a Watercourse Reached? If YES, Volume Impacting the Watercourse RECEIVED as a Watercourse was Impacted, Describe Fully.* JAN 1 5 2008 scribe Cause of Problem and Remedial Action Taken.* During purging activities discovered leak in the 6 inch pipeline testimg Brieflese of Problem and Remedial Action Taken.* The impacted soil was excavated and stockpiled on plastic. Aerial extent of surface impact was proximately 6,500 square feet. scribe Area Affected and Cleanup Action Taken.* The impacted soil was excavated and stockpiled on plastic. Aerial extent of surface impact was proximately 6,500 square feet. ereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and utations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger plic health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of fiability to compliance with any other eral, state or local laws and/or regulations anture: and/or period by District Supervisor: anterweet to group water, surface water, human health environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other eral, state oreloca								
as Immediate Notice Given? as Immediate Notice Given? If YES, To Whom? Pat Richards Date and Hour 01/04/2008@ 14:25 is a Watercourse Reached? If YES, Volume Impacting the Watercourse RECEIVED a Watercourse was Impacted, Describe Fully.* JAN 1 5 2008 escribe Cause of Problem and Remedial Action Taken.* During purging activities discovered leak in the 6 inch pipeline Galling Errolese of Order Oriclamp was installed on the line to mitigate the release. The line is idle so information concerning volume and pressure is unavailable. escribe Area Affected and Cleanup Action Taken.* The impacted soil was excavated and stockpiled on plastic. Aerial extent of surface impact was proximately 6,500 square feet. ereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and gulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger blic health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of responsibility for compliance with any other terenvironment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other terenvironment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other terenvironment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other terenvironment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any othe	urce of Release 6" Steel Pipeline							
Yes No Not Required Pat Richards Whom? Camille Reynolds Date and Hour 01/04/2008@ 14:25 as a Watercourse Reached? If YES, Volume Impacting the Watercourse RECEIVED a Watercourse was Impacted, Describe Fully.* JAN 1.5 2008 a Watercourse was Impacted, Describe Fully.* JAN 1.5 2008 scribe Cause of Problem and Remedial Action Taken.* During purging activities discovered leak in the 6 inch pipeline estimation concerning volume and pressure is unavailable. scribe Cause of Problem and Remedial Action Taken.* The impacted soil was excavated and stockpiled on plastic. Aerial extent of surface impact was proximately 6,500 square feet. scribe Area Affected and Cleanup Action Taken.* The impacted soil was excavated and stockpiled on plastic. Aerial extent of surface impact was proximately 6,500 square feet. ereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and pulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger blic health or the environment. The acceptance of a C-141 report dues not relieve the operator of responsibility of compliance with any other eral, state-orticcal laws and/or regulations. mature OIL CONSERVATION DIVISION mature Approval Date: S 08 Expirat@OMELANCE OFFICER nate Name: Camille Reynolds Approval Date: S 08 Expirat	as Immediate Notice Given?				01/04/200)8 @ 11:45		
A Watercourse Reached? Yes No If YES, Volume Impacting the Watercourse RECEIVED JAN 1 5 2008 HOBBS OCC Scribe Cause of Problem and Remedial Action Taken.* During purging activities discovered leak in the 6 inch pipeline resulting methods of the release. The line is idle so information concerning volume and pressure is unavailable. Scribe Area Affected and Cleanup Action Taken.* The impacted soil was excavated and stockpiled on plastic. Aerial extent of surface impact was proximately 6,500 square feet. Ereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and gulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger for ble heavior ment. The acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other eral, state or local laws and/or regulations. Mathematical Coordinator Approved by District Supervisor: Approved by District Supervisor: Approved by District Supervisor: Approval Date: OIL CONSERVATION DIVISION Approval Date: OIL CON		Not Required						
A Watercourse was Impacted, Describe Fully.* JAN 1 5 2008 scribe Cause of Problem and Remedial Action Taken.* During purging activities discovered leak in the 6 inch pipeline resulting metches of Public frequency of the information of the release. The line is idle so information concerning volume and pressure is unavailable. scribe Area Affected and Cleanup Action Taken.* The impacted soil was excavated and stockpiled on plastic. Aerial extent of surface impact was proximately 6,500 square feet. seribe vertify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and utations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger ble health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of responsibility for compliance with any other eral, state or local laws and/or regulations. Market and the report does not relieve the operator of acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other eral, state or local laws and/or regulations. Market and the norted by District Supervisor: Market Approved Date: Market Approved Barket Approved Market Ap	Whom? Camille Reynolds		Date and H	our 01/04/2008@) 14:25			
A Watercourse was Impacted, Describe Fully.* JAN 1 5 2008 Scribe Cause of Problem and Remedial Action Taken.* During purging activities discovered leak in the 6 inch pipeline resulting meterse of Pure Problem and Remedial Action Taken.* During purging activities discovered leak in the 6 inch pipeline resulting meterse of Pure Problem and Pressure is unavailable. Scribe Area Affected and Cleanup Action Taken.* The impacted soil was excavated and stockpiled on plastic. Aerial extent of surface impact was proximately 6,500 square feet. Scribe Area Affected and Cleanup Action Taken.* The impacted soil was excavated and stockpiled on plastic. Aerial extent of surface impact was proximately 6,500 square feet. Scribe Area Affected and Cleanup Action Taken.* The impacted soil was excavated and stockpiled on plastic. Aerial extent of surface impact was proximately 6,500 square feet. Scribe Area Affected and Cleanup Action Taken.* The impacted soil was excavated and stockpiled on plastic. Aerial extent of surface impact was proximately 6,500 square feet. Scribe Area Affected and Cleanup Action Taken.* The impacted soil was excavated and stockpiled on plastic. Aerial extent of surface impact was proximately 6,500 square feet. Scribe Area Affected and Cleanup Action Taken.* The impacted soil was excavated and stockpiled on plastic. Aerial extent of surface impact was proximately 6,500 square feet. Scribe Area Affected and Cleanup Action Taken.* The impacted soil was excavated and stockpiled on plastic. Aerial extent of surface impact was proximately 6,500 square feet. Scribe Area Affected and Cleanup Action Taken.* The impacted soil was excavated and stockpiled on plastic. Aerial extent of Surface impact was proximately 6,500 square feet. Scribe Area Affected and Cleanup Action Taken.* The impact descentration that possibility for compliance with any other real, state or, local laws and/or regulations. Scribe Area Affected and Coordinator Scribe Area Affected and Action Taken.* The impacted soil was excavated	as a Watercourse Reached?		If YES, Vo	lume Impacting t	he Watercourse	RECEMEN		
JAN 1 5 2008 scribe Cause of Problem and Remedial Action Taken.* During purging activities discovered leak in the 6 inch pipeline relative processor is unavailable. clamp was installed on the line to mitigate the release. The line is idle so information concerning volume and pressure is unavailable. scribe Area Affected and Cleanup Action Taken.* The impacted soil was excavated and stockpiled on plastic. Aerial extent of surface impact was roximately 6,500 square feet. rereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and ulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger plic health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability uld their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other eral, state, or local laws and/or regulations nature: OIL CONSERVATION DIVISION nature: Approved by District Supervisor: nature: Approved by District Supervisor: nature: Approval Date: 1/5/08 Expirat@OMARLIANCE OFFICER nature: Approval Date: 1/5/08 Expirat@OMARLIANCE OFFICER nail Address: ci	Yes X No				×.	l Lan V has I V has he		
scribe Cause of Problem and Remedial Action Taken.* During purging activities discovered leak in the 6 inch pipeline resulting BESE Occurs leamp was installed on the line to mitigate the release. The line is idle so information concerning volume and pressure is unavailable. scribe Area Affected and Cleanup Action Taken.* The impacted soil was excavated and stockpiled on plastic. Aerial extent of surface impact was proximately 6,500 square feet. scribe Area Affected and Cleanup Action Taken.* The impacted soil was excavated and stockpiled on plastic. Aerial extent of surface impact was proximately 6,500 square feet. scribe Area Affected and Cleanup Action Taken.* The impacted soil was excavated and stockpiled on plastic. Aerial extent of surface impact was proximately 6,500 square feet. scribe Area Affected and Cleanup Action Taken.* The impacted soil was excavated and stockpiled on plastic. Aerial extent of surface impact was proximately 6,500 square feet. scribe Area Affected and Cleanup Action Taken.* The impacted soil was excavated and stockpiled on plastic. Aerial extent of surface impact was proximately 6,500 square feet. scribe Area Affected and Cleanup Action Taken.* The impacted soil was excavated and stockpiled on plastic. Aerial extent of surface impact was provided by operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger plic health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of fisability put their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, human health the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other real, state-oxfocal laws and/or regulations the Remediation Coordinator nature:	Watercourse was Impacted, Describe Fully.*							
ereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and gulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger blic health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability bould their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other teral, state or local laws and/or regulations. OIL CONSERVATION DIVISION near Camille Reynolds te: Remediation Coordinator nail Address: cjreynolds@paalp.com Phone:505-441-0965 Phone:505-441-0965 Phone:505-441-0965	scribe Area Affected and Cleanup Action Taken.* T	he impacted soil wa	as excavated	and stockpiled on	plastic. Aerial ex	tent of surface impact was		
gulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger blic health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability build their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other teral, state or local laws and/or regulations.	proximately 6,500 square feet.							
gulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger blic health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability build their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other teral, state or local laws and/or regulations.	· · · ·							
OIL CONSERVATION DIVISION gnature: OIL CONSERVATION DIVISION inted Name: Camille Reynolds Approved by District Supervisor: OIL CONSERVATION DIVISION inted Name: Camille Reynolds Approved by District Supervisor: OIL CONSERVATION DIVISION inted Name: Camille Reynolds Approved by District Supervisor: OIL CONSERVATION DIVISION inted Name: Camille Reynolds Approval Date: ISO 8 Expiration MartillANCE OFFICER intel Address: cjreynolds@paalp.com Conditions of Approval: Attached Intel Attached te: 01/09/2008 Phone:505-441-0965 Malutinal Optical for the Wool Attached Intel Attached	gulations all operators are required to report and/or fil ublic health or the environment. The acceptance of a C nould their operations have failed to adequately investi- the environment. In addition, NMOCD acceptance o	e certain release no C-141 report by the gate and remediate	otifications an NMOCD ma contaminatio	d perform correc wrked as "Final Re on that pose a thre	tive actions for rele eport" does not reli eat to ground water	eases which may endanger leve the operator of liability surface water, human health		
inted Name: Camille Reynolds Approved by District Supervisor: Image: Approved by District Supervisor: ile: Remediation Coordinator Approval Date: Image: Solution Solution Image: Solution Solution intel Address: cjreynolds@paalp.com Conditions of Approval: Image: Solution Solution Image: Solution Solution te: 01/09/2008 Phone: 505-441-0965 Image: Solution Solution Image: Solution Solution Image: Solution Solution				OIL CONS	SERVATION	DIVISION		
inted Name: Camille Reynolds Approved by District Supervisor: Image: Approved by District Supervisor: ile: Remediation Coordinator Approval Date: Image: Solution Solution Image: Solution Solution intel Address: cjreynolds@paalp.com Conditions of Approval: Image: Solution Solution Image: Solution Solution te: 01/09/2008 Phone: 505-441-0965 Image: Solution Solution Image: Solution Solution Image: Solution Solution	gnature: amile KECMO	las			\sim	\sim .		
nail Address: cjreynolds@paalp.com te: 01/09/2008 Phone:505-441-0965 Conditions of Approval: Attached At	inted Name: Camille Reynolds	1	Approved by	District Supervise	r: PA	Richardo		
nail Address: cjreynolds@paalp.com te: 01/09/2008 Phone:505-441-0965 Conditions of Approval: Attached At	tle: Remediation Coordinator		Approval Date	11510	8 Expiration	WRLIANCE OFFICER		
te: 01/09/2008 Phone: 505-441-0965 analytical data & final Attached []	E-mail Address: cirevnolds@paaln.com			Conditions of Approval:				
		Conclustical dollar & line Attached []'						
report due by: RPH171	tach Additional Sheets If Necessary		Villand	LIUS UNIX	and junas			
		<i></i>	Nepor	l due	Luf:-	RP#171		