

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	ConocoPhillips Company	Contact	Mickey Garner
Address	3300 North A St. Bldg 6, Midland, TX 79705-5406	Telephone No.	505.391.3158
Facility Name	EVGSAU 2060-055	Facility Type	Oil and Gas

Surface Owner	State of New Mexico	Mineral Owner	State of New Mexico	Lease No	30-025-02843-00-00
---------------	---------------------	---------------	---------------------	----------	--------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	20	17S	35E					Lea

Latitude N 32 49.135 Longitude W 103 29.302

NATURE OF RELEASE

Type of Release Crude oil and produced water	Volume of Release 13bbl (2oil, 11water)	Volume Recovered (2oil, 8water)
Source of Release 2 3/8" steel flowline	Date and Hour of Occurrence 1/23/2008 1200	Date and Hour of Discovery 1/23/2008 1440
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*
N/A



Describe Cause of Problem and Remedial Action Taken.*

On Wednesday January 23, 2008 at 1440 hrs a leak was discovered coming from a 2 3/8" steel flowline on EVGSAU #2060-055 due to external corrosion. Amount spilled was 2 bbls of oil and 11 bbls of produced water. The spill was not contained and affected approximately 900 sq/ft of pasture. The Contract MSO called a vacuum truck to pick up the free liquids. 2 bbls of oil and 8 bbls of produced water were recovered. Chloride concentration for this area is 48,000.

Describe Area Affected and Cleanup Action Taken.*

The spill was not contained and affected approximately 900 sq/ft of pasture. The flowline leak was found by a COPC Contract Employee. The Contract MSO called a vacuum truck to pick up the free liquids. 2 bbls of oil and 8 bbls of produced water were recovered. The spill site will be remediated in accordance with NMOCD guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Mickey Garner		Approved by District Supervisor: 	
Title: HSER Lead		Approval Date: 1/20/08	Expiration Date: 4/30/08
E-mail Address: Mickey.D.Garner@conocophillips.com		Conditions of Approval:	
Date: 1-28-08 Phone: 575.391.3158		Attached <input type="checkbox"/>	

RP#1767