

1R - 426-143

REPORTS

DATE:

4-1-08

BD Jct K-7-3

1R426-143

CLOSURE

4 - 1 - 08

RICE OPERATING COMPANY
JUNCTION BOX FINAL REPORT

BOX LOCATION

SWD SYSTEM	JUNCTION	UNIT	SECTION	TOWNSHIP	RANGE	COUNTY	NEW BOX DIMENSIONS - FEET		
Blilnebry-Drinkard (BD)	jct. K-7-3	K	7	22S	37E	Lea	Length	Width	Depth
							no box-junction eliminated		

LAND TYPE: BLM _____ STATE _____ FEE LANDOWNER Colonial Securities Co. OTHER _____

Depth to Groundwater 190 feet NMOCD SITE ASSESSMENT RANKING SCORE: 0

Date Started 6/22/2007 Date Completed 7/13/2007 NMOCD Witness no

Soil Excavated 2 cubic yards Excavation Length 4 Width 4 Depth 3 feet

Soil Disposed 0 cubic yards Offsite Facility n/a Location n/a

FINAL ANALYTICAL RESULTS: Sample Date 6/22/2007 Sample Depth 6 ft

TPH and chloride laboratory test results completed by using an approved laboratory and testing procedures pursuant to NMOCD guidelines.

CHLORIDE FIELD TESTS

Sample Location	PID (field) ppm	GRO mg/kg	DRO mg/kg	Chloride mg/kg
HAND AUGER GRAB 6 ft below jct.	-----	<25	117	<16

LOCATION	DEPTH (ft)	ppm
background	0.5	175
below junction	6	181

General Description of Remedial Action:

This junction box was moved/upgraded as part of the pipeline replacement program.

Once the box lumber was removed from the former site, the location was inspected for chloride and hydrocarbon impact. The soils at and around the site were of a brown sand type and did not exhibit any staining or other signs of adverse impact. The surrounding surface has a healthy vegetation cover and does not appear to be stressed. Field tests on the soil samples confirmed that chloride were very low, similar to those of background. Confirmation samples were analyzed at a certified laboratory. The 4 x 4 x 3-ft hole was backfilled and the disturbed surface area was seeded with a blend of native vegetation on 7/13/2007 and is expected to return to productive capacity at a normal rate.

enclosures: photos, lab results

I HEREBY CERTIFY THAT THE INFORMATION ABOVE IS TRUE AND COMPLETE TO THE BEST OF MY
KNOWLEDGE AND BELIEF.

SITE SUPERVISOR Darnell Mitchell SIGNATURE Darnell Mitchell COMPANY RICE Operating Company

REPORT ASSEMBLED BY Kristin Farris Pope SIGNATURE Kristin Farris Pope

DATE 8/27/2007 TITLE Project Scientist

BD jct. K-7-3



undisturbed junction box

4/2/2004



former junction box site

6/21/2007



backfilling hole

7/13/2007



seeding disturbed area of backfilled site

7/13/2007



ARDINAL LABORATORIES

PHONE (325) 673-7001 • 2111 BEECHWOOD • ABILENE, TX 79603

PHONE (505) 393-2326 • 1015 MARLAND • HOBBS, NM 88240

RECEIVED

ANALYTICAL RESULTS FOR
RICE OPERATING CO.
ATTN: ROY R. RASCON
122 W. TAYLOR
HOBBS, NM 88240
FAX TO: (505) 397-1471

JUL 02 2007
RICE OPERATING
HOBBS NM

Receiving Date: 06/26/07
Reporting Date: 06/29/07
Project Number: NOT GIVEN
Project Name: NOT GIVEN
Project Location: BD K-7-3 JCT.

Sampling Date: 06/22/07
Sample Type: SOIL
Sample Condition: COOL & INTACT
Sample Received By: LB
Analyzed By: LB/HM

LAB NUMBER	SAMPLE ID	GRO (C ₆ -C ₁₂) (mg/Kg)	DRO (>C ₁₂ -C ₂₈) (mg/Kg)	Cl* (mg/Kg)
------------	-----------	--	--	----------------

ANALYSIS DATE	06/27/07	06/27/07	06/26/07
H12807-1 Source 6'	<25.0	117	<16
Quality Control	856	778	500
True Value QC	1000	1000	500
% Recovery	85.6	77.8	100
Relative Percent Difference	3.9	11.6	1.0

METHODS: TPH GRO & DRO: EPA SW-846 8015 M; Cl: Std. Methods 4500-ClB

*Analysis performed on a 1:4 w:v aqueous extract.

COPY

L. R. Rascon
Chemist

6/29/07
Date

H12807A RICE

PLEASE NOTE: Liability and Damages. Cardinal's liability and client's exclusive remedy for any claim arising, whether based in contract or tort, shall be limited to the amount paid by client for analyses. All claims, including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including, without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or successors arising out of or related to the performance of services hereunder by Cardinal, regardless of whether such claim is based upon any of the above-stated reasons or otherwise.

ORDINAL LABORATORIES, INC.

2111 Beechwood, Adilene, TX 79603 101 East Marland, Hobbs, NM 88240
(325) 673-7001 Fax (325) 673-7020 (505) 393-2326 Fax (505) 393-2476

CHAIN-OF-CUSTODY AND ANALYSIS REQUEST

[illegible]