District I
1625 N. French Dr , Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr , Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action OPERATOR Initial Report Final Report Contact Mickey Garner Name of Company ConocoPhillips Company Address 3300 North A St. Bldg 6, Midland, TX 79705-5406 Telephone No. 505.391.3158 Facility Name MCA 2-C Production Header Facility Type Oil and Gas Mineral Owner BLM Surface Owner BLM Lease No 30-025-00743 MCA#178 LOCATION OF RELEASE Unit Letter Township Range Feet from the North/South Line Feet from the East/West Line County Section 28 17S 32E Lea Latitude N 32.80380 Longitude W 103.76968 NATURE OF RELEASE Volume Recovered Type of Release Volume of Release (Ooil, Owater) **Crude Oil and Produced Water** 31bbl (16oil, 15water) Source of Release Date and Hour of Occurrence Date and Hour of Discovery 05-19-2008 0800 14" collar 05-19-2008 1445 Was Immediate Notice Given? If YES, To Whom? Chris Williams By Whom? Mickey Garner Date and Hour 05-20-2008 1520 Was a Watercourse Reached? If YES, Volume Impacting the Watercourse. ☐ Yes ⊠ No N/A MAY 2 1 2008 If a Watercourse was Impacted, Describe Fully.* N/A Describe Cause of Problem and Remedial Action Taken.* On Monday May 19, 2008 at 1445 hrs, a leak was discovered coming from a buried 14" fiberglass line at MCA 2-C Production Header, which is located 1 mile south of the Maljamar Production Office. Amount spilled was 15 bbls of produced water and 16 bbls of crude oil. The spill was not contained an affected approximately 16,500 sq ft of pasture. No fluid was recovered. CHLORIDE OF DITR Describe Area Affected and Cleanup Action Taken.* Upon arrival, the MSO started isolating the line. The source of discharge was a 14" fiberglass collar that separated from the pipe. The area will be remediated in accordance with NMOCD guidelines. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. OIL CONSERVATION DIVISION Signature: Approved by District Supervisor: Printed Name: Mickey Garner Title: HSER Lead Approval Date: Expiration Date: E-mail Address: Mickey.D.Garner@conocophillips.com Conditions of Approval:

Phone: 575.391.3158