3R-1006

Release Report/ General Correspondence

Date April, 2008 District 1
1625 N French Dr , Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr , Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Revised October 10, 2003

Form C-141

Release Notification and Corrective Action

					OPERATOR				al Report		Final Report		
Name of Company XTO Energy Inc.						Contact Kim Champlin							
Address #382 County Road 3100						Telephone No. (505) 333-3100							
Aztec, NM 87410													
Facility Name Mr. Nona 15 #1 (API 30-045-30318)						Facility Type Gas Well							
Surface Owner Federal Mineral Owner						Lease No. NMNM023473							
LOCATION OF RELEASE													
Unit Letter	Section	Township	Range	Feet from the	North/	South Line	Feet from the	East/W	Vest Line County				
E	15	30N	14W	1938	North	710 West San Ju				San Juan			
	Latitude <u>36.816018</u> Longitude <u>108.303108</u>												
	NATURE OF RELEASE												
Type of Rele	ase Produ					Recovered	Recovered Approx 0 bbl						
Source of Re				· · · · · · · · · · · · · · · · · · ·	lour of Occurren	Date and Hour of Discovery							
						03/14/08, time unknown			03/14/08 3:00 PM				
Was Immediate Notice Given?						If YES, To		RCVD APR 1'08					
		\boxtimes	equired		Powell- OCD	OIL CONS. DIV.							
By Whom? Kim Champlin						Track Recity District							
Was a Water				Date and Hour 03/17/08 10:00AM DIST. 3 If YES, Volume Impacting the Watercourse.									
∑ Yes □ No						Approximately 30 bbl							
If a Watercou	urse was Im	pacted, Descr	ibe Fully.	*		I							
If a Watercourse was Impacted, Describe Fully.* Produced water entered Coolidge Arroyo, that runs parallel to the pipeline, and traveled approximately 340 feet down the wash. Due to recent													
snow melt and obvious run off in the arroyo it is undetermined how much produced water entered the arroyo. Samples were collected along the													
area of the wash where the impact occurred.													
	Describe Cause of Problem and Remedial Action Taken * A lease operator noticed a water leak in a pipeline that was thought to have been isolated and abandoned. Upon investigation it was discovered that there was no isolation valve and thawing process had caused extra pressure to build up												
				produced water									
				n recent snow me									
Appropriate	notificatio	ons were mad	le and san	nples were collec					311				
		and Cleanup											
				tubing was close								were	
collected and after review of the results any required treatment of affected areas will be determined. A final report will be submitted.													
				e is true and comp									
				nd/or file certain i									
				ce of a C-141 rep									
				/ investigate and i									
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations													
	1		OIL CONSERVATION DIVISION										
	ih.												
Signature.	r/lm	Chan	w		Approved by District Supervisor. Brandon A. M. Remin								
Printed Nam	e: Kim Ch	amplin			Approved by District Supervisor. Brandon Towell Perrin								
Title: Environmental Representative													
litte: Envir	onmental l	Kepresentativ		-	Approval Date: 4-1-08			Expiration Date:					
E-mail Address: Kim Champlin@xtoenergy.com						Conditions of Approval Attached							
Date 03/	27/08		505-333-3100										

^{*} Attach Additional Sheets If Necessary