

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Chesapeake Energy	Contact: Bradley Blevins
Address: 1616 west Bender Boulevard	Telephone No.: 575-441-0341
Facility Name: Millard Deck Estate 28 Fed 1	Facility Type

Surface Owner	Mineral Owner	Lease No.
---------------	---------------	-----------

LOCATION OF RELEASE

API# 30.025.38103.00.00

Unit Letter B	Section 28	Township 22S	Range 36e	Feet from the 965	North/South Line <input checked="" type="radio"/> North <input type="radio"/> South	Feet from the 1590	East/West Line <input checked="" type="radio"/> East <input type="radio"/> West	County Lea
------------------	---------------	-----------------	--------------	----------------------	--	-----------------------	--	---------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 20 barrels	Volume Recovered: 15 barrels
Source of Release: Lightning Strike to Battery	Date and Hour of Occurrence: 10-5-08 3:30pm	Date and Hour of Discovery: 10-5-08 4:00pm
Was Immediate Notice Given? Required x <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not	If YES, To Whom? Left Message for Mark W.	
By Whom? Bradley Blevins	Date and Hour 10-6-08	
Was a Watercourse Reached? <input type="checkbox"/> Yes x <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

DEPTH TO GW = 300' ±

Describe Cause of Problem and Remedial Action Taken.*

Lightning struck water tank, releasing 20 barrels of produced water to firewall, 15 barrels of the fluid was recovered by vac trucks. Firewall is lined with plastic liner. The bottom of the liner was not damaged.

Describe Area Affected and Cleanup Action Taken.*

Vac trucks recovered the fluid from the firewall. Damaged tank has been removed and will be replaced with a new tank.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Bradley Blevins</u>		OIL CONSERVATION DIVISION	
Printed Name: <u>Bradley Blevins</u>		Approved by District Supervisor: <u>Jeffrey Belkin</u>	
Title: <u>EHS</u>	Approval Date: <u>10.07.08</u>	Expiration Date: <u>12.07.08</u>	
E-mail Address: <u>bblevins@che.com</u>	Conditions of Approval: <u>PHOTOS OF NEW TANK INSTALLATION AND REPAIRED LINER</u>		Attached <input type="checkbox"/>
Date: <u>10-7-08</u>	Phone:		

* Attach Additional Sheets If Necessary

FGRL0829452484

IRP-1970