

District I  
1625 N. French Dr., Hobbs, NM 88240 ✓  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised October 10, 2003

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

RECEIVED  
FEB 23 2009

HOBBSDOCD  
Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company : Chevron	Contact : Ricky Heredia
Address ; P.O. Drawer 29	Telephone No. : 432-523-3655 ext 7603
Facility Name : West Dollarhide Drinkard Unit	Facility Type : Water Station

Surface Owner : Chevron	Mineral Owner	Lease No.
-------------------------	---------------	-----------

LOCATION OF RELEASE

NEARBY WELL 30-025-30823-00-00

Unit Letter D	Section 32	Township 24S	Range 38 E	Feet from the	North/South Line	Feet from the	East/West Line	County
------------------	---------------	-----------------	---------------	---------------	------------------	---------------	----------------	--------

Latitude \_N 32 10.291' \_ Longitude \_W 103 05.339 \_

NATURE OF RELEASE

Type of Release : Produce Water	Volume of Release : 158 bbls	Volume Recovered : 60 bbls
Source of Release	Date and Hour of Occurrence	Date and Hour of Discovery
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Called OCD	
By Whom? Ricky Heredia	Date and Hour : 02/17/2009 @ 14:30	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*  
NA

WATER @ 100'



Describe Cause of Problem and Remedial Action Taken.\*

Internal Corrosion on 2" Steel IPC nipple from Water Injection Station failed releasing 158 bbls produce water

Describe Area Affected and Cleanup Action Taken.\*

Upon discovery mobilized one call brought in vacuum truck, Isolated and repaired leak, Recovered 60 bbls produce water, called Third party to do permanent remediation of release site

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Ricky Heredia	Approved by District Supervisor: 	
Title: HES Specialist	Approval Date: 02/25/09	Expiration Date: 04/20/09
E-mail Address: rhrc@chevron.com	Conditions of Approval: DECON/REMEDIATION - FINAL C-141 DUE	Attached <input type="checkbox"/>
Date: 02/20/2009 Phone: 432-523-3655 ext 7603	RP-09-02-2108	

\* Attach Additional Sheets If Necessary

FGRL0905660588