District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Revised October 10, 2003


Form C-141

Release Notification and Corrective Action


		OPERA	OR		✓ Initia	al Report	□ F	inal Report	
Name of Company Plains Pipeline, LP	(Contact	Jason Henr	y					
Address 2530 Hwy 214 – Denver City, TX 79323]	Telephone N	lo. (575) 441-1	099					
Facility Name Chevron Grayburg 6-inch	F	Facility Typ	e Pipeline						
Surface Owner NMSLO Mineral Ow	ner	Lease No.							
LOCATION OF RELEASE									
		South Line	Feet from the	East/We	est Line	County	County		
B 2 18S 34E						Lea			
Latitude N 32.78043° Longitude W 103.52933° N									
NATURE OF RELEASE									
Type of Release Crude Oil						olume Recovered 0 bbls			
Source of Release 6" Steel Pipeline			Date and Hour of Occurrence			Date and Hour of Discovery			
Was Immediate Notice Given?			07/08/2009 07/ If YES, To Whom?			7/08/2009 @ 13:40			
☐ Yes ☐ No ☒ Not Required									
By Whom? Jason Henry			our 07/30/200			·········			
Was a Watercourse Reached?		If YES, Volume Impacting the Watercourse.							
☐ Yes ☒ No									
If a Watercourse was Impacted, Describe Fully.*	RECEIVED								
JUL 2 9 2009									
Describe Cause of Problem and Remedial Action Taken.*					HOBBSOCD				
External corrosion of Chevron Grayburg 6" pipeline caused a release of crude oil. Throughput for the subject line is 1,750 bbls/day and the operating pressure of the pipeline is 60 psi. The depth of the pipeline at the release point is approximately <1 bgs. The H2S concentration in the crude is less than 10 ppm and the gravity of the crude is 36.									
Describe Area Affected and Cleanup Action Taken.* .									
The released crude resulted in a surface stain that measured approximately 4' x 4'. The impacted area will be remediated per applicable guidelines.									
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.									
// $A/$		OIL CONSERVATION DIVISION							
Signature: Jason Henry			6	I ohnson					
Printed Name: Jason Henry	Α	Approved by District SUPPLY SOUNMENTAL ENGINEER							
Title: Remediation Coordinator	A	Approval Date: 7.30.09 Expiration Date: 10.1.09							
E-mail Address: jhenry@paalp.com	c	Conditions of	Approval:			Attached			
Date: 07-30-2009 Phone: (575) 441-1099		IRP# 09.7.2743					243		


* Attach Additional Sheets If Necessarv

FGRL 0921727039



View to the southeast of release point and new 6-inch pipe (7-8-2009)







Northwest sidewall of excavation and surface completion of out of service water supply well? (7-27-2009)

