District II Energy Mineral	f New Mexico s and Natural Resource REC	DEIVED Form C-141 Revised March 17, 1999
District III Oil Conse	ervation Division FE	3 - 5 2010 Submit 2 Copies to appropriate District Office in accordance
District IV 1220 Sou	th St. Francis Dr. Fe, NM 87505 NMOC	CD ARTESIA with Rule 116 on back side of form
	on and Corrective Acti	
0 MLB 0 9222 4000 2 OPERATOR Initial Report S Final Report		
Name of Company BTA Oil Producers LLC 260297 Contact Pam Inskeep		
Address 104 S. Pecos, Midland, TX 79701 Telephone No.□ (432) 682-3753 Facility Name Pardue -B-, 8808 JV-P Facility Type□ Well		
Surface Owner Mississippi Potash Mineral Owner Kirby Minerals, Teledyne Indust. Lease No.		
LOCATION OF RELEASE		
	h/South Line Feet from the Ea	st/West Line County□ est Eddy
NATURE OF RELEASE		
Type of Release Major Source of Release Lightning Strike	Volume of Release 285 bbls Date and Hour of Occurrence	Volume Recovered I0 bblsDate and Hour of Discovery I
	11 pm CDT, 7/29/2009	11 pm CDT, 7/29/2009
Was Immediate Notice Given? If YES, To Whom? Yes No Not Required Sherry Bonham, Artesia		
By Whom? □ Clay Tipton, Field Supervisor Date and Hour□ 11:30 pm CDT 7/29/2009 Was a Watercourse Reached? If YES, Volume Impacting the Watercourse.		
□ Yes ⊠ No		
If a Watercourse was Impacted, Describe Fully.*		
N/A		
Describe Cause of Problem and Remedial Action Taken.* Gary Tucker, pumper, and the Loving Fire Department were both called by the landowner. Upon arriving at the location, the pumper found the location engulfed in flames. The field supervisor was immediately notified. One oil tank had been struck and blown into the air and had landed on production equipment on the site. All oil in the affected tank and one other tank was burned up. A portion of the oil stored in a third tank was transferred to our Pardue D battery (very close in proximity E-11-23S-28E and producing from the same reservoir). The remainder of the stock in the third tank was lost and destroyed by the flames. A vacuum truck was brought in Approximately 200 bbls of produced water was recovered and taken to an approved disposal. The remainder of the water burned and/or evaporated. All of the affected area is within the firewall.		
After contractors removed all damaged surface equipment, an environmental contractor was mobilized to perform remediation activities at the site All impacted soil was removed and disposed of at an approved disposal facility. Samples were collected from the excavation and were submitted to a laboratory and analyzed for DRO, GRO, BTEX and Chlorides All samples were found to be below regulatory limits and the excavation was backfilled with clean soil purchased from a nearby source*. A representative of the Artesia OCD office inspected the site during remediation activities The remediation was completed on 11/09/09. We have been waiting for the State seed mixture recommendation		
There are no further remediation activities planned for this site A new battery site was constructed just north of the original battery. A single sheet of 20-mil poly-liner was used to line the new battery floor and berms The poly-liner was draped over an earthen berm and then covered with caliche		
* The site is not seeded, to date, as we have not received the seed mixture recommended from the State.		
Describe Area Affected and Cleanup Action Taken.*		
See above explanation		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
OIL CONSERVATION DIVISION		
Signature: K/M MWW left Approved by Bigned Bypervisor		
Printed Name: Pam Inskeep	MAY 2 6 2010	
Title: Regulatory Administrator	Approval Date:	Attached
Date: 02/03/2010 Phone: (432) 682-3753	Conditions of Approval: An	2RP-326