

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED
MAY 27 2010
HOBBSCOCD

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

X Initial Report ☐ Final Report

Name of Company	Wagner & Brown, Ltd. (24499)	Contact	Brian Ramey
Address	P.O. Box 1714	Telephone No.	432-686-5935
Facility Name	Brenda #1 (API #30-025-22965)	Facility Type	Pumping Oil Well
Surface Owner	Ray Hilburn	Mineral Owner	George Coates
		Lease No.	Fee

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	19	11S	33E	1980'	South Line	660'	East Line	Lea

Latitude 33.3492400 Longitude -103.646800 TS

NATURE OF RELEASE

Type of Release	Oil Tank Leak	Volume of Release	180 Bbls	Volume Recovered	none
Source of Release	Stock Tank	Date and Hour of Occurrence	5/25/2010 ?	Date and Hour of Discovery	5/25/2010 +- 3:00 PM
Was Immediate Notice Given?	X Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Geoffrey R. Leking.		
By Whom?	Brian Ramey	Date and Hour	5/26/2010 10:00 AM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes X No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

A hole developed in the bottom of the oil stock tank causing the escape of oil from the tank into the firewall area surrounding the tank. When discovered, the tank was isolated from production. Tank will be replaced and/or repaired.

Describe Area Affected and Cleanup Action Taken.*

The area affected was contained inside the firewall around the stock tank. Attempted to recover standing oil inside the firewall, none was recovered.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Brian Ramey		ENV ENGINEER : Approved by District Supervisor: 	
Title: Operations Manager		Approval Date: 07/19/10	Expiration Date: 09/20/10
E-mail Address: bramey@wbld.com		Conditions of Approval: DELINEATE VERTICAL AND HORIZONTAL EXTENT OF CONTAMINATION. REMEDIATE TO OGD STANDARDS. SUBMIT TO OGD	
Date: May 26, 2010 Phone: 432-686-5935		Attached <input type="checkbox"/> IRP-10.7.2587	

* Attach Additional Sheets If Necessary

THE FINAL C-141 BY 09/20/10