District I 1625 N. French Dr. Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III
1000 Rto Brazos Road, Aztec NM 87410
District IV
1220 S St Francis Dr. Santa Fc, NM 87505

State of New Mexico Energy Minerals and Natural Resources SEP 29 2010

RECEIVED

Form C-141 vised October 10, 2003

side of form

NMOCD ARTESIA Copies to appropriate Office in accordance with Rule 116 on back fide or form

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Release Notification and Corrective Action  OPERATOR  Initial Report  Final Report			
ame of Company OGRID Number		Contact Emilia Report	T Hitt (CDX/II
Yates Petroleum Corporation 25575		Amanda Trujillo	
Address		Telephone No.	
104 S. 4 <sup>10</sup> Street		575-748-1471	E STATE OF BEHAVE SECURE SECUR
Facility Name API Number Mobil CI #8 30-015-2327	- 1	Facility Type Order Num Oil well 2RP- 440	ibei
		OH WEIL 2RT - 440	
Surface Owner Mineral C Fee BLM	Owner ———	Lease No.	
LOCATION OF RELEASE			
Unit Letter   Section   Township   Range   Feet from the   1   6   19S   25E   1650			ounty DDY
Latitude N33.13240 Longitude W104 13323  NATURE OF RELEASE			
Type of Release		Volume of Release Volume Reco	vered
		8 0	.210
Source of Release Date and Hour of Occu Broken Flowline 9/18/2010			ir of Discovery M
Was Immediate Notice Given? If YES, To Whom?			
		Date and Hour (99/201/2010 pm)	
Amanda Trujillo – Yates Petroleum Corporation Was a Watercourse Reached?		09/29/2010 pm  If YES, Volume Impacting the Watercourse.	
Yes ⊠ No		N/A	
If a Watercourse was Impacted, Describe Fully.*  N/A			
Describe Cause of Problem and Remedial Action Taken.*  FLowline ruptured in the pasture. The well was shut in and crews were dispatched to excavate contaminated material and make necessary repairs and remedial steps.  Describe Area Affected and Cleanup Action Taken.*  An approximate size of 50° \ 50° was impacted. The impacted area is located in the pasture northwest of well. Soil from the pooling areas was excavated and disposed of at an NMOCD approved facility. Vertical and horizontal defunction samples will taken and analysis ran for TPH and BTEX once all contaminated material has been removed. Chlorides analysis upon request. Depth to Ground Water: >100° (approx. 305°, per New Mexico State Engineers Office): Wellhead Protection Area: No; Distance to Surface Water Body: >1000°; SITE RANKING IS 0. Based on site ground water quality and enclosed analytical results.  Thereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health of the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.  OIL CONSERVATION DIVISION  Signed By Mile Beauty Bea			
Title Environmental Scientist		Approval Date: SEP 3 0 2010 Expiration Date.	
Date Wednesday, September 29, 2010 Phone, 575-748-4, Attach Additional Sheets If Necessary  nMG/0273 39/44	310	REMEDIATION per OCD Rules and Guidelines. SUBMIT REMEDIATION	RRP-440
nMYB1027339144  pmys 1027339505  Chloride analysis Required			

## Bratcher, Mike, EMNRD

From:

Amanda Trujillo [atrujillo@yatespetroleum.com]

Sent:

Wednesday, September 29, 2010 2:45 PM

To:

Bratcher, Mike, EMNRD

Subject:

Mobil CL #8

Attachments:

Mobil CI #8 (9-18-2010 Inital).pdf

Mr. Mike Bratcher:

Yates Petroleum reports a release at the following location:

Mobil CL #8

Sec. 6, Township 19 South, Range 25 East

**Eddy County** 

Date of Release: 9/18/2010

Approximately 8 barrels of oil were released; 0 recovered Cause of release has been isolated and repairs are in progress

Site will be evaluated and a work plan for remediation will be submitted for consideration

Attached is the C-141

If you should have any questions please feel free to contact me at the number below.

Amanda N. Trujillo
Environmental Scientist
Yates Petroleum Corporation
Office 575-748-4310
Cell 575-703-6537
Email atrujillo@yatespetroleum.com

## Bratcher, Mike, EMNRD

From: Alan & Cheryl [ahowell@pvtnetworks.net]
Sent: Monday, September 20, 2010 9:24 AM
Amanda Trujillo: LooPay Richards

To: Amanda Trujillo; LeeRoy Richards

Cc: Lisa Norton; Jerry Fanning; James\_Amos@blm.gov; Bratcher, Mike, EMNRD

Subject: Mobile Cl #8 Section 6, 19s, 25e

Attachments: Pipe came apart at the seam 9-18-2010 010.jpg

## Amanda & LeeRoy,

You have probably already heard that we have had another leak on the pipline for the Mobile CI # 8. I don't know how long it had been leaking but the ground is saturated & the vegetation is already dying. (picture attached) This is the second leak in the last few months on this pipeline & the third one in about a year or so. This is also the area that has had multiple leaks that have not been cleaned up & the contamination still needs to be addressed.

Please call me when you visit the site. I would like for you to address all of the contaminated areas in the pasture from the pipelines going to the Mobil CI Battery B. These were on the list Lisa asked me to send to you in April & I have not received a response as of yet. We need to move forward & address these issues, other lists of issues are still pending.

Thank You,

Cheryl

