District I 1625 N. French Dr., Hobbs, NM 88240	State of New Mexico Energy Minerals and Natural Resources				Form C-141 Revised October 10, 2003		
1301 W. Grand Avenue, Artesia, NM 88210 <u>District III</u> 1000 Rio Brazos Road, Aztec, NM 87410 District IV	Oil Conservation Division 1220 South St. Francis Dr.				Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back		
1220 S. St. Francis Dr. Santa Fe, NM 87505 Santa Fe, NM 87505						side of form	
Release Notification and Corrective Action							
1M4B1025938939		OPERA			itial Report	Final Report	
Name of Company COG OPERATING LLC 2: Address 550 W. Texas, Suite 100 Midland, TX 797		Contact Kanicia Carrillo Telephone No. 432-685-4332					
Facility Name – Muskegon 16 State Com #1 – Sk		Facility Type- Battery					
Surface Owner State Mineral Owner			Lease No. 30-015-27108				
LOCATION OF RELEASE							
Unit LetterSectionTownshipRangeFeet fromN1617S29E660		th/South Line	Feet from the 1980	East/West Lin West	e County Eddy		
	I i				<u> </u>		
Latitude Longitude							
NATURE OF RELEASE Type of Release-10 bbls oil, 40 bbls produced water Volume of Release-50 bbls Volume Recovered- 35 bbls (5-oil,30w)						35 hble (5 oil 30utr)	
Source of Release- Tank			Hour of Occurrence	nce- Date and Hour of Discovery			
Was Immediate Notice Given?			10/28/09 Approx. 1:16pm 10/28/09 Approx. 1:16pm If YES, To Whom?				
Yes No Not Required							
By Whom? Pat Ellis			Date and Hour 10/28/09 2:43pm				
Was a Watercourse Reached?			If YES, Volume Impacting the Watercourse.				
If a Watercourse was Impacted, Describe Fully.*							
Describe Cause of Problem and Remedial Action Taken.*							
The tank overflowed duc to a pump malfunction.							
Describe Area Affected and Cleanup Action Taken.* The release stayed on the pad and entrance road.							
Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for your approval prior to any significant remediation work.							
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and							
regulations all operators are required to report and/or file ce	rtain release	notifications an	nd perform correct	ive actions for	releases which	may endanger	
public health or the environment. The acceptance of a C-14 should their operations have failed to adequately investigate	and remedi	ate contaminati	on that pose a thre	at to ground wa	iter, surface wa	ter, human health	
or the environment. In addition, NMOCD acceptance of a C federal, state, or local laws and/or regulations.	C-141 report	does not relieve	e the operator of re	esponsibility fo	r compliance w	ith any other	
			OIL CONS	ERVATIO	N DIVISIC	<u>N</u>	
Signature: Al			Approved by District Briston Branciscon				
E-mail Address: kcarrillo@conchoresources.com	IFCes com						
Date: 11/11/09 Phone: 432-685-433	2		INTION DER OC	D Rules and	Attached		
Attach Additional Sheets If Necessary	Necessary			IEDIATION			
PMGB 1025939495 PROPOSAL BY: PIAM REC'D 2RP-43							
			4/22/	0		•	

atter sa anne

Bratcher, Mike, EMNRD

From: Sent: To: Subject: Pat Ellis [PEllis@conchoresources.com] Wednesday, October 28, 2009 2:43 PM Bratcher, Mike, EMNRD Muskeegon SWD

Mike.

I was just notified that we had a 50 bbl spill on our Muskeegon 16 State Com #1 battery. Unit N Sec.16-T17S-R29E. 660FSL. 1980FWL Eddy Co. API#30-015-27108. Approximately 10 bbls of oil and 40 bbls produced water. We picked up 35bbls (5 bbls oil, 30 bbls water). We will assess and send in a C-141. Thanks, Pat.

Patrick Ellis EH&S Advisor COG OPERATING LLC 550 W. Texas Avenue, Suite 100 Midland, Texas 79701 Office 432.686.3023 Cell 432.230.0077 Fax 432.687.8008

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

This inbound email has been scanned for malicious software and transmitted safely to you using Webroot Email Security.