

District I  
1625 N French Dr., Hobbs, NM 88240  
District II  
1301 W Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**RECEIVED**

JAN 26 2011

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
Office in accordance  
with Rule 116 on back  
side of form

30-015-22700

**Release Notification and Corrective Action**

nkmw/1103249928

**OPERATOR**☒ Initial Report ☐ Final Report

Name of Company Range Resources Corporation 227588	Contact: Steve Almager
Address: 100 Throckmorton Ste 1200	Telephone No. (575)394-1485
Facility Name: SCB #3	Facility Type: Battery
Surface Owner	Mineral Owner
Lease No.	

**LOCATION OF RELEASE**

Unit Letter G	Section 23	Township 23 S	Range 28 E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	------------------	---------------	---------------	------------------	---------------	----------------	----------------

Latitude: 32.29299 N Longitude: 104.05589 W

**NATURE OF RELEASE**

Type of Release Produced Fluids	Volume of Release ~250 bbls	Volume Recovered 210 bbls
Source of Release: Eroded Union; Pump Failure	Date and Hour of Occurrence 1/25/11 6 am	Date and Hour of Discovery 1/25/11 6:30 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher, NMOCD	
By Whom? Sergio Contreras, SESI	Date and Hour 1/25/11 2:30 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

The union of the tank eroded off, causing the pump to fail and shut off. As a result of the pump failure, approximately 250 bbls of produced fluids was released within the firewalls of the tank battery.

Describe Area Affected and Cleanup Action Taken.\*

SESI was contacted for assessment. Area will be delineated and an appropriate work plan submitted upon results.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Steve Almager	Approved by District Supervisor: 	
Title: Production Supervisor II	Approval Date: 3/9/11	Expiration Date:
E-mail Address: salmager@rangeresources.com	Conditions of Approval:	
Date: 1/25/11 Phone: (575) 394-1485	Remediation per OCD Rules & Guidelines. <b>SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:</b>	

\* Attach Additional Sheets If Necessary

4/9/11

2 RP-599

## **Bratcher, Mike, EMNRD**

---

**From:** Susana Rodriguez [office2@sesi-nm.com]  
**Sent:** Wednesday, January 26, 2011 9:46 AM  
**To:** Bratcher, Mike, EMNRD  
**Subject:** RE: Initial C-141 SCB #3  
**Attachments:** C-141 SCB#3.pdf

Mr. Bratcher:

Attached please find the initial C-141 for the SCB #3 for Range Resources.

Thank you,

***Susana Rodriguez***  
***Administrative Assistant***  
***Safety & Environmental Solutions, Inc.***  
***O: 575.397.0510***  
***F: 575.393.4388***