OIL CONSERVATION DIVISION 2040 South Pacheco Street Santa Fe, New Mexico 87505 (505) 827-7131

June 5, 1997

MR Drilling Company P.O. Box 687 Monahans, Texas 79756

Attention: Chris Hisel

Re:

Wills Federal Well No. 1 Unit D, Section 34-26S-37E

Lea County, New Mexico

Dear Mr. Hisel:

The Oil Conservation Division recently received a complaint concerning the surface injection pressure being utilized at the Wills Federal Well No. 1 salt water disposal well. In response to this complaint, the Division conducted a field visit to the facility on May 22, 1997. The OCD Field Representative noted that pump pressure was 1175 psi. The authorized maximum surface injection pressure for this well, as contained within Division Order No. SWD-641 is 644 psi.

You are hereby directed to immediately cease injection into the subject well at a surface injection pressure in excess of 644 psi. Failure to comply with this directive will result in the termination of injection authority and/or the imposition of a fine of \$1000.00 per day.

If an increase in surface injection pressure is necessary, please be advised that such increase can only be approved after the conductance of a step-rate injection test which demonstrates that injection at such higher pressure will not result in the fracture of the injection formation or confining strata..

If you should have any questions, please contact me at (505) 827-8184.

Sincerely,

David Catanach UIC Director

xc:

OCD-Hobbs File-SWD-641 UIC Violation File

M R DRILLING COMPANY

P.O. BOX 687 MONAHANS, TEXAS 79756

A Vis right

June 13, 1997

Mr. David Catanach, UIC Director
New Mexico Energy, Minerals & Natural Resources Department
Oil Conservation Division
2040 S Pacheco St.
Santa Fe, NM 87505

Re: Wills Federal Well No. 1 Unit D, Section 34-26S-R37E Lea County, New Mexico

Dear Mr. Catanach:

Thank you for your letter of June 5, 1997. Prior to the inspection of the Wills Federal #1 by the OCD Field Representative, MR Drilling had attempted to ameliorate the pressure increase through backflowing the well and acidizing the injection interval, without success. On or about the date of the inspection MR had shut this well in and was trucking the produced water to disposal.

The problem with this well is a lack of permeability in the injection zone. The offset operator, Smith & Marrs, has indicated he will protest application for a pressure increase, and the well will most likely need to be re-fraced to allow injection at reduced pressure.

We are currently studying this situation as to the best solution. We will notify your office with our proposal as soon as this study is complete. If I can answer any questions concerning the Wills Federal #1, please call me at (915) 943-2501.

Sincerely,

Chris Hisel

General Manager

3 4 4 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	JUN- LASSIPICATION	4-0	7 WE		21 PM OCD HOBBS FAX NO. 15053930720 P. 1 Attn: David Catanach Charlie Perrin Boto 5-12-97 Niles 95 District Time of Departure 7 AM Sine of Return 4 PM Car No. G- In the space below indicate the purpose of the trip and the duties performed, listing wells or lesses visited and any action taken. Rightness	154(
7	V	C	1.		Hobbs Shell? 1HU 4 RHT 31-221, 33-121 29-421, 32-421	
0	J	5	1		PRESSON PUMP 950 Punt Ran 3 min Held @ 1175 when Ru.	. <u>P</u>
M	0	ρ	/		Kicked off fell 70 1000 slow drop 10 950 1 Loc 541 MARAIO JAIMAT VATES BYTY AREA WORKED 1 Loc 541 noeth Oxy MLMV #28 30-23-36 AREA WORKED	
<i>H</i>	U	C	5		House keeling on Texaco Gw sims GPII Amst m APAche skelly PenRose Ledbetter Lulamae Anadarko Langu Collins Lwale swalden Hendrix walden A PenRose Clower ST Bettis Boxle & SXOVA 11, Pat	Sey
					Hilesee 150 Per Daum Hours 7 UIC UIC UIC 7 HFA RFA RFA Other 45 Other Other	-
-		: इस्की स्टब्स	78878 (E)	DN .	INSPECTION MATURE OF SPECIFIC V CLASSIFICATION OR PACILITY INSTE	
		Paup Paup Well Ress Water Mann	TOO! LP/MI LP/MI MP G! MP G!	Chee	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	247* QO _
		~ /	'49 ()		

The state of the s

96490