



United States Department of the Interior

BUREAU OF LAND MANAGEMENT
Pecos District
Carlsbad Field Office
620 E. Greene
Carlsbad, New Mexico 88220-6292
www.blm.gov/nm



RECEIVED OGD
2013 FEB -4 P 1:26

IN REPLY REFER TO:
3162.3-2 (P0220)

Oil Conservation Division
1220 South St. Francis Drive
Santa Fe, NM 87505

FEB 01 2013

Re: Application of Frontier Field Services, LLC's motion to Amend Order No. R-13443.

The BLM will object to the above request to Amend Order No. R-13443 to eliminating the requirements that Frontier place H2S warning flags or safety indicators on and potentially plug the identified and any later-completed offset wells. Please note that the wells mentioned in the reference order are Federal wellbores and will require federal approval for revision. The Maljamar AGI #1 was approved based upon the fact that the reference order will be enforced.

How does placing a H2S warning flag impair correlative rights and result in waste?

If you have any questions regarding this approval, please contact Edward G Fernandez, Petroleum Engineer at (575) 234-2220 or Wesley Ingram, Supervisory Petroleum Engineer at (575) 234-5982.

Sincerely,

Don Peterson
Assistant Field Manager,
Lands and Minerals
Bureau of Land Management
Carlsbad Field Office

cc: Geolex