

Research

- Build database
 - Identify all directional wells
 - Correct BHL's
- Identify all quarter sections with more than 2 wells
- Identify all quarter-quarter sections with more than 1 well
- Review previous infill pilot approvals for exceptions
- Verify company ownership
- Research well files to verify non-compliant wells
- Finalize list of non-compliant wells

Results

Location	Fm	Violation	Current Status
T28N-R7W-S18-SW	MV	3 completions in quarter section	Paperwork error. Reported abandonment of MV in SJU 28-7 #30 as TA rather than P&A. Problem has been corrected.
T30N-R6W-S2-SW	MV	3 completions in quarter section, 2 in quarter-quarter	Preparing to abandon MV in SJU 31-6 #15, (currently SI), as per original plan.
T31N-R8W-S32-SE	MV	3 completions in quarter section	High deliverability area with checkerboard leasing. Preparing to abandon or isolate MV in State Com AL #36 (currently SI).
T28N-R7W-S34-NE	MV	2 completions in quarter-quarter section	SJU 28-7 #91 (MV) currently SI. Request exception to pool rules.
T29N-R5W-S34-NE	MV	2 completions in quarter-quarter section	SJU 29-5 #34 currently SI. Request exception to pool rules.
T28N-R7W-S24-SW	DK	2 completions in quarter-quarter section	SJU 28-7 #259 currently SI. Request exception to pool rules.