Form 3160-5 (April 2004)

#### OCD-ARTI UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

	FORM APPROVED OMB No. 1004-0137 Expens: March 31, 200
-	

Month - Year MAR 2 3 2007 OCD - ARTESIA, NM

SUNDRY NOTICES AND REPORTS ON WEL Do not use this form for proposals to drill or to re-enter an abandoned wall. Use Form 3160-5 (APD) for such proposals.

SUBMIT IN TRIPLICATE- Other instructions on reverse side.

Other

Gas Well

NM070603 6. If Indian, Allottee or Tribe Name 7. If Unit or CA/Agreement, Name and/or No. 8. Well Name and No. Shearn Saranda Federal #1 9. AM Well No. 30-015-31060

1. Type of Well X Oil Well 2. Name of Opensor C & D Management Company 231382 la Address 513 Don Lyle Road 3b. Phone No. (include area code) 270-565-4629 Edmonton, KY 42129 10. Field and Pool, or Exploratory Area Empire Yates 7 Rivers 4. Location of Well (Foologie, Sec., T., R., M., or Survey Description) 11. County or Parish, State 1226' FNL & 1106' FEL (Unit A) Section 14-T17S-R27E

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF ACTION TYPE OF SUBMISSION Acidize Docpon Production (Start/Resume) Water Shut-Off Notice of Intent Alter Caung Fracture Treat Reclamation Well Integrity Casing Repair New Construction Recomplete Subsequent Report Plug and Abandon Change Plans Temporarily Abandon Final Abandonment Notice Convert to Injection Plug Back Water Dispusal

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filled once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

We are proposing to plug and abandon the above well by placing a plug at bottom of hole and 25 sacks Class C cement then placing a plug at top of 25 sacks Class C cement. Total depth of well is 650 feet. This well is under bond #NMB0002455

# SEE ATTACHED FOR CONDITIONS OF APPROVAL

14. Thereby certify that the foregoing is true and correct Name (Printed Typed) Darla Jeffries		President				
Signature Narlas Jeddails	Deste	12 March 07		APPROVED		
THIS SPACE FOR FEDERAL OR STATE OFFICE USE						
			<del> </del>			
Approved by		Title	Dete	MAD 2 1 2007		
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		Office	1	MAN LICEN		
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department in The LEV Of the United RAM States any false, factitious or fraudulent statements or representations as to any matter within its jurisdiction.  PETROLEUM ENGINEER						
(Instructions on page 2)						

Accepted for record NMOCD

Case 14055 De Novo C&D Management Company dba Freedom Ventures Company OCD Exhibit 80

## Shearn Saranda Federal #1 C & D Management Company March 21, 2007 Plug and Abandon Procedure

Plug at bottom of hole must be of sufficient length to reach 50 feet above uppermost perforation.

Surface plug must extend to 300 feet to provide adequate protection for fresh water zone.

WWI 032107

Accepted for record NMOCD

# BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 505-234-5972

### Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the  $90^{\rm th}$  day provide this office, prior to the  $90^{\rm th}$  day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 505-627-0272; Eddy County, call 505-234-5972; Lea County, call 505-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. In lieu of a cement plug in a cased hole, a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 50 feet of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either class "C", for up to 7,500 feet of depth, mixed at 14.8 lbs/gal with 6.3 gallons of fresh water per sack or class "H", for deeper than 7,500 feet plugs, mixed at 16.4 lbs/gal with 4.3 gallons of fresh water per sack.

- 6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement. The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).
- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and five copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date well was plugged</u>.
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration conditions of approval will be developed and furnished to you.

Accepted for record