

23-Feb-10

## Well Inspection History

API Number: **30-015-35435-00-00**

Well Name & No.: **OWL 20504 JV-P**

Operator: **BTA OIL PRODUCERS, LLC, PAM INSKEEP** District: **ARTESIA** County Name: **EDDY**

Field: **OWL 20504 JV-P**

Legal: **S: 18 T: 26S R: 27E**

Well Type: **OIL (PRODUCING)**

Insp. Dt.	Insp. Type	Insp. Purpose	Insp. No.	RmdyRqDt	Insp. By	Viol. SNC	Failed Codes
2/18/2010	Routine/Periodic	Normal Routine Activity	iREI10049450		213		
This is an unauthorized injection well. Around 480psi on tubing. Injection pump on mercury switch. Electricity box set to ON and AUTO.							
1/28/2010	Routine/Periodic	Normal Routine Activity	iREI10028285		213		
BLM reports operator is injecting into this well. SWD 1091 expires 8/10/08. Operator has no authority to inject. No production or injection being reported to OCD.							
8/26/2009	Routine/Periodic	Normal Routine Activity	iKMW0923837		215		
Change status, everything in great shape,							
9/22/2008	File and Compliance Review	Normal Routine Activity	iSEB08266274		217		
Initial C141							
8/6/2007	File and Compliance Review	Normal Routine Activity	iMLB07218380		211		
C-144 drilling pit closure approved for dig and haul to disposal.							
6/12/2007	Routine/Periodic	Normal Routine Activity	iGEG0716327		209		
4/20/2007	Routine/Periodic	Normal Routine Activity	iPAC07255310		197		
blm - followup inspection for surface csg cmtg on 04/20/07 revealed the following problems: 1. 3m BOPE system w/o annular preventer installed. 2. No hand wheels on ram preventers, no remote controls accesible to friller. 3. Only 1 power supply to accumulator system (drilling contractor had not commenced drilling operations at this time). Written orders were issued on these problems and operator was informed to make correction prior to drilling out the surface shoe. PET Jerry Blakley was contacted to travel to location and confirm compliance. Compliance was achieved, written orders were signed off on, inspection was closed.							
4/10/2007	Routine/Periodic	Normal Routine Activity	iREI07141551		213		
Spill Notification from PAM Release in tank battery 20-30 barrels w/in lined dyke. Recovered 20 barrels. Advised submit proper paperwork.							

**Total Inspections Performed: 8**

Case 14559  
BTA Oil Producers LLC

~~(OGD-Exhibit D)~~

1 of 1