

Gum, Tim

From: KEITH BUCY[SMTP:KEBUCY@basspet.com]
Sent: Tuesday, November 21, 2000 4:55 PM
To: Joe Lara; Mary Jo Rugwell; Jim Amos; Steve Salzman; Tim Gum
Subject: Plan of Action for Inactive Bass-Operated Wells in New Mexico



Bass_inactive.xls



ATT62696.txt

On November 8, I met with BLM reps in Carlsbad and discussed in detail Bass' plans for its inactive wells in New Mexico. Please find attached an Excel spreadsheet with a summary of the results of that meeting.

If you have any questions, give me a call.

Keith E. Bucy
Division Production Supt.
Bass Enterprises Prod. Co.
915/683-2277

BEFORE EXAMINER STOGNER	
OIL CONSERVATION DIVISION	
OCD	EXHIBIT NO. 15
CASE NO.	12811

		Inactive				
WELL		Date	Current Wellbore Configuration		Plan of Action	
Bass 3 Federal #1		Jul-95	Left rods & tbg in hole.	PxA		
Bass 10 Federal #2		Sep-93	TA'd 9/12/97: LD rods & tbg, MIT - 750 psi.		Request TA extension. Plan to return to prod by re-installing RxB lift.	
Big Eddy #10		Dec-89	TA'd 12/89: LD tbg, MIT - 500 psi. 5/98: MIT - 500 psi		Request TA approval. Plan to recomplete to Bone Spring.	
Big Eddy #33		May-00	Left rods & tbg in hole.		Return to production. Re-design rod string.	
Big Eddy #38		Apr-90	TA'd 6/94: Set CIBP, circ pkr fluid, MIT - 500 psi, left tbg in hole.		Recomplete to Bone Spring.	
Big Eddy #40		Sep-78	TA'd 10/78: Left tbg, RTTS pkr & RBP in hole; MIT 6/98: 500 psi		Request TA extension. Possible directional well in Strawn.	
Big Eddy #41		Dec-87	Left 2-7/8" tbg in hole; MIT 4/95: 550 psi		Request TA approval. Run MIT. Return to prod in LP system or recomplete to Bone Spring.	
Big Eddy #44		Aug-98	Left tbg and pkr in hole		Request TA approval. Run MIT. Engr to review for frac stimulation.	
Big Eddy #54		Jun-95	Left tbg and pkr in hole; Tstd csg to 1000 psi 5/95 during recompletion.		Request TA approval. Run MIT. Return to prod or recomplete to Wolfcamp	
Big Eddy #60		Dec-82	Left tbg and pkr in hole		Not on Federal acreage. Run MIT for NMOCD.	
Big Eddy #64		Sep-96	Left tbg in hole, LD rods and pump.		Return to prod within 60 days. Re-install RxB lift.	
Big Eddy #66		Jan-97	Left tbg and pkr in hole; Tstd csg to 1000 psi 4/95 during recompletion		Request TA approval. Run MIT. Return to prod in LP gas system.	
Big Eddy #70		Feb-90	Left tbg and pkr in hole; MIT 3/95: 590 psi.		Request TA approval. Run MIT. Return to prod or recomplete to Morrow and frac stimulate.	
Big Eddy #71		Jan-85	TA'd 1/96: Left tbg in hole; MIT 1/96: 530 psi		Request TA approval. Run MIT. Recomplete to Delaware.	
Big Eddy #73		Feb-98	Left tbg and pkr in hole		Return to prod within 60 days by installing RxB lift.	
Big Eddy #80		Mar-88	Left tbg and pkr in hole; MIT 3/95: 580 psi		Request TA approval. Run MIT. Test Lower Morrow or recomplete to Bone Spring.	
Big Eddy #83		Jan-85	Left tbg and pkr in hole; MIT 10/93: 590 psi		Request TA approval. Run MIT. Recomplete to Bone Spring or Delaware.	

Big Eddy #84	Jun-92	Left tbg and pkr in hole.	Request TA approval. Run MIT. Hold for future SWD.
Big Eddy #92	May-97	Left tbg and pkr in hole.	Return to prod within 60 days by installing compression or tying into LP gas system.
	Inactive		
<u>WELL</u>	<u>Date</u>	<u>Current Wellbore Configuration</u>	<u>Plan of Action</u>
Big Eddy #93	Aug-92	Left tbg and pkr in hole; Tsid csg to 2000 psi 7/92 during recompletion.	Request TA approval. Run MIT. Return to prod in LP gas system.
Big Eddy #94	Nov-95	Left tbg and pkr in hole.	Return to prod by 1/17/00 by installing RxB lift.
Big Eddy #133	Jan-00	Left tbg and rods in hole.	Return to prod within 60 days.
Golden 8 Federal #4	Apr-95	TA'd 10/99; Left tbg in hole; MIT 10/99: 500 psi	Request TA extension. Run MIT. Convert to SWD.
Hopeful Federal #1	Mar-86	TA'd 7/98; Nothing in hole; MIT 3/95: 560 psi.	PxA. May have to drill out upper CIBP.
James Ranch #10	Jul-97	Tbg and pkr in hole	Return to prod within 60 days. Change out tbg or recomplete to Morrow.
Merchant State #4	Jan-97	PxA. Left flange on wellhead for easy re-entry. all necessary cmt plugs in place	Not on Federal acreage
Poker Lake #41	Dec-99	TA'd 6/00; Left tbg in hole; MIT 6/00: 500 psi	Review old frac stimulation study by RMC.
Poker Lake #42	Jun-83	Workover in progress to recomplete in Morrow	Return to prod in Morrow or Wolfcamp.
Poker Lake #49	May-93	TA'd 5/95; Left tbg and pkr in hole; MIT 5/95: 540 psi	Request TA approval. Run MIT. Return to prod in one of various zones.
Poker Lake #52	Mar-95	Left tbg and pkr in hole; MIT 3/95: 540 psi	Request TA approval. Run MIT. Recomplete to Wolfcamp.
Poker Lake #57	Jun-95	TA'd 6/95; Nothing in hole; MIT 6/95: 530 psi.	Request TA approval. Run MIT. Recomplete to Bone Spring.
Poker Lake #58	Jan-95	TA'd 1/93; Left 1000' tbg in hole; MIT 3/95: 520 psi	Request TA approval. Run MIT. Possible sidetrack to Morrow.
Poker Lake #60	Oct-91	Rods and tbg in hole	PxA.
Poker Lake #91	Dec-99	Rods and tbg in hole	Request TA approval. Run MIT. Hold for SWD.

Poker Lake #98	Dec-97	Nothing in hole, Waiting on BLM approval for conversion to SWD.	WO BLM surface approval for conversion to SWD.
Rodke Federal #2	May-95	TA'd 5/95; Left rods and tbg in hole; MIT 5/95: 500 psi	Request TA extension. Run MIT. Possible sidetrack to Delaware. BLM has denied several Delaware APD's in this area due to potash. Cancel sundry requesting PxA approval.