




10,000

7500

5000

2500

0

PRODUCTION - BBL'S.

S.B. ROSE No. 1

Oil

Water

Put on Pump

1949

1950

1951

1952

1953

10000

7500

5000

2500

0

PRODUCTION - BBL'S.

EAVES "A" No. 1

COOPER 2

Water

Put on Pump

Oil

1951

1952

1951

1952

JAN. FEB. MAR. APR. MAY JUNE JULY AUG. SEP. OCT. NOV. DEC. JAN. FEB. MAR. APR. MAY JUNE JULY AUG. SEP. OCT. NOV. DEC. JAN. FEB. MAR. APR. MAY JUNE JULY AUG. SEP. OCT. NOV. DEC. JAN. FEB. MAR. APR. MAY JUNE JULY AUG. SEP. OCT. NOV. DEC.