


After much study, it is our opinion there are no corrosive fluids or heaving formation from bottom of 9-5/8 to top of cement.

BEFORE EXAMINER UTZ
OIL CONSERVATION COMMISSION
EXHIBIT NO. 1
CASE NO. 1949

TRICE PRODUCTION COMPANY
LONGVIEW, TEXAS

DIAGRAM OF PROPOSED COMPLETION
TRICE PRODUCTION COMPANY
#1 FOUR LAKES STATE
LEA COUNTY, NEW MEXICO



After much study, it is our opinion there are no corrosive fluids or heaving formation from bottom of 9-5/8 to top of cement.

ILLEGIBLE

TRICE PRODUCTION COMPANY
 LONGVIEW, TEXAS

DIAGRAM OF PROPOSED COMPLETION
 TRICE PRODUCTION COMPANY
 #1 FOUR LAKES STATE
 LEA COUNTY, NEW MEXICO