

2231

LIVINGSTON RIDGE


LOS MEDANOS, E.

SAND DUNES, NO.

SAND DUNES, W.

SAND DUNES

<p>Richardson Oil 1-1-61(2) 44827</p> <p>24</p>	<p>S.R. Bass Thru Line Inc. et al HBU 069509</p> <p>19</p>	<p>Richardson Oil HBU 069507</p> <p>20</p>	<p>Gulf 7-1-64 21772</p> <p>21</p>	<p>R.N. Enfield 8-1-75 0419982</p> <p>22</p>	<p>Pogo 7-1-90 62583 482 M KGS</p> <p>23</p>	<p>Texaco (Getty Fed. Atoka Disc.) (5 Mil) Del. Disc. P206</p> <p>24</p>
<p>Richardson Oil 1-1-61(3) 44827</p> <p>25</p>	<p>S.R. Bass Thru Line Inc. et al HBU 069509</p> <p>30</p>	<p>Richardson Oil HBU 069508 (2)</p> <p>29</p>	<p>Superior 12-1-85 26387</p> <p>28</p>	<p>Gulf 12-1-83 19616</p> <p>27</p>	<p>Pogo 7-1-90 62590 532 M KGS</p> <p>26</p>	<p>Pogo Prod Feb. NEFF Merr. Disc. 10,150 G C4 19 86</p> <p>25</p>
<p>Richardson Oil 1-1-61(2) 44827</p> <p>36</p>	<p>Conoco HBU 02953</p> <p>31</p>	<p>Gulf 3-1-77 K6777 2743</p> <p>32</p>	<p>Flag-Reedfern 5-17-75 K6008 1703</p> <p>33</p>	<p>Gulf 12-1-83 19616</p> <p>34</p>	<p>M.P. Grace 9-1-73 0481054</p> <p>35</p>	<p>Union 11-90 V1313 732 M</p> <p>36</p>
<p>Richardson Oil 1-1-61(2) 44827</p> <p>11</p>	<p>Bass Ent. HBU 02887</p> <p>6</p>	<p>Richardson Oil HBU 02887</p> <p>5</p>	<p>Yates Pet. et al Santa Fe Ener. 1/2 9-1-94 81953 208</p> <p>4</p>	<p>Yates Pet. et al Santa Fe Ener. 1/2 9-1-94 81953 208</p> <p>3</p>	<p>Yates Pet. et al Santa Fe Ener. 1/2 9-1-94 81953 208</p> <p>2</p>	<p>Union 10-1-97 V8-213 302 M</p> <p>1</p>
<p>Richardson Oil HBU 02887</p> <p>12</p>	<p>Bass Ent. HBU 02887</p> <p>7</p>	<p>Richardson Oil HBU 02887</p> <p>8</p>	<p>Santa Fe Ener. 9-1-93 77046 6500</p> <p>9</p>	<p>Santa Fe Ener. 9-1-93 77046 6500</p> <p>10</p>	<p>Pogo Prod 5-1-93 59300 342 M KGS</p> <p>11</p>	<p>Marathon, et al 040441</p> <p>12</p>
<p>Phillips P 2516</p> <p>13</p>	<p>Conoco HBU 02887</p> <p>14</p>	<p>Richardson Oil HBU 02887</p> <p>15</p>	<p>Santa Fe Ener. (Terra Res.) 45235</p> <p>16</p>	<p>Yates Pet. V-120</p> <p>16</p>	<p>Devon Ener. HBP 0405444</p> <p>15</p>	<p>Devon Ener. 4-1-74 0533177</p> <p>14</p>
<p>Phillips 32516</p> <p>24</p>	<p>Shell 6-1-74 0546237</p> <p>18</p>	<p>Shell 6-1-74 0546237</p> <p>17</p>	<p>Phillips 4-1-74 0533177</p> <p>19</p>	<p>Phillips 4-1-74 0533177</p> <p>20</p>	<p>Phillips 4-1-74 0533177</p> <p>21</p>	<p>Phillips 4-1-74 0533177</p> <p>22</p>
<p>Phillips 3532341</p> <p>25</p>	<p>Phillips 4-1-74 0533177</p> <p>30</p>	<p>Phillips 6-1-74 0545039</p> <p>29</p>	<p>Phillips 6-1-74 0545039</p> <p>28</p>	<p>Phillips 6-1-74 0545039</p> <p>27</p>	<p>Phillips 6-1-74 0545039</p> <p>26</p>	<p>Phillips 6-1-74 0545039</p> <p>25</p>



BEFORE EXAMINER CATANACH  
OIL CONSERVATION DIVISION  
Yates EXHIBIT NO. 1  
CASE NO. 18049