

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

| | |
|------------------------|--|
| NO. OF COPIES RECEIVED | |
| DISTRIBUTION | |
| SANTA FE | |
| FILE | |
| U.S.G.S. | |
| LAND OFFICE | |
| OPERATOR | |

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease
State ☒ Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

| | |
|---|---|
| 1. OIL <input type="checkbox"/> GAS <input type="checkbox"/> OTHER- Dry | 7. Unit Agreement Name |
| 2. Name of Operator Exxon Corporation | 8. Farm or Lease Name Dennis |
| 3. Address of Operator P. O. Box 1600, Midland, TX 79702 | 9. Well No. 1 |
| 4. Location of Well UNIT LETTER m 1141 FEET FROM THE West LINE AND 691 FEET FROM THE South LINE, SECTION 32 TOWNSHIP 8N RANGE 33E NMPM. | 10. Field and Pool, or Wildcat Wildcat |
| 15. Elevation (Show whether DF, RT, GR, etc.) 4705' GR | 12. County Quay |

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

| | | | |
|--|---|--|--|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/> | CHANGE PLANS <input type="checkbox"/> | COMMENCE DRILLING OPNS. <input type="checkbox"/> | PLUG AND ABANDONMENT <input checked="" type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | OTHER <input type="checkbox"/> | CASING TEST AND CEMENT JOBS <input type="checkbox"/> | |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Cement plugs were set as follows:

7-22-81 Spot plug 6600-6750' w/100 sx ClH
Spot plug 5800-6140' w/200 sx ClH
8-21-81 Set CIBP @ 5000'; cap w/35' cmt.
9-18-81 Set retainer @ 3031' and pumped 50 sx ClC on top.
10- 1-81 Set plug 2400-3026' w/35 sx ClC
10- 3-81 Set plug 1650-1765' w/35 sx ClC
Set plug 10-Surface w/10 sx ClC
10- 6-81 Install dry hole marker

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Charlotte Harper TITLE Accountant DATE 10-26-81

APPROVED BY Carl Wilcox TITLE SENIOR PETROLEUM GEOLOGIST DATE 2/17/82

CONDITIONS OF APPROVAL, IF ANY: