

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	☒
U.S.O.B.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.
LG - 5582

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - 1" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☐	GAS WELL ☒	OTHER: _____
Name of Operator		
The Desana Corporation		
Address of Operator		
600 Bldg. of the Southwest, Midland, Texas 79701		
Location of Well		
UNIT LETTER	M	660
FEET FROM THE West LINE AND 660 FEET FROM		
THE south LINE, SECTION 36 TOWNSHIP 5-N RANGE 30-E NMPM.		

7. Unit Agreement Name
8. Farm or Lease Name
Wichita - State
9. Well No.
1
10. Field and Pool, or Wildcat
Wildcat
12. County
QUAY

15. Elevation (Show whether DF, RT, GR, etc.)

4602.1 GL

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK	☐
TEMPORARILY ABANDON	☐
PULL OR ALTER CASING	☐
OTHER	☐
PLUG AND ABANDON	☒
CHANGE PLANS	☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK	☐
COMMENCE DRILLING OPER.	☐
CASING TEST AND CEMENT JOB	☐
OTHER	☐
ALTERING CASING	☐
PLUG AND ABANDONMENT	☐

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.


PRESENT STATUS

1-14-83 TD - 7150 Plug back 50Sx plug 6300-6400, 100 Sx plug 4800-4900, 120 Sx plug 3300-3400, 50 Sx plug 2467-2560.
1-17-83 PBTD 2467 set 4-1/2" csg 10.50# @ 2464 cmt w/ 700 Sx.
3-10-83 PBTD 2449, perf 2423-25, 2428-31, acidize w/ 250 gal.
3-13-83 Set CIBP 2414 cap w/1 Sx cmt. Perf 2382-85 treat w/ 250 gal Zylene & 500 gal acid.
3-16-83 Set CIBP 2375 cap w/1 Sx cmt. Perf 2349-53 & 2362-64 acidize w/ 250 gal
3-22-83 Set CIBP 2335 cap w/2 Sx cmt. Perf 2070-83, 2085-87, 2089-91 acidize w/ 2500 gal.
4-05-83 Ran 4 pt test.
8-15-83 File temporary abandon notice

PROPOSED OPERATION:

Set CIBP @ 2050 cap w/2 Sx cmt. TIH w/ tbg to 2000'. Circ hole w/ 10.0# mud. TOOH w/ tbg.
Shoot off 4-1/2" csg @ 1600'. Lay down csg. TIH w/ tbg to 1650 set 25 Sx Class "C" plug.
(50' in 4-1/2, 50' in 10" avg. hole) Set #2 plug 55 Sx Class "C" @ 1025' (50' in Avg. 11" hole & 50' in 8-5/8 csg).
Set 15 Sx Class "C" plug @ 50' TD Surface. Weld cap on 8-5/8 pipe. Install dry hole marker.

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED		Grant Thayer	TITLE		DATE	4-01-86
APPROVED BY			TITLE	Sr. Pet. Geologist	DATE	4-9-86
CONDITIONS OF APPROVAL, IF ANY:						