

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	
U.S.O.B.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-105  
Revised 10-1-78

JAN 24 1983

OIL CONSERVATION DIVISION

5a. Indicate Type of Lease  
State ☒ Fee ☐

5. State Oil & Gas Lease No.  
LG 5582

SUNDRY NOTICES AND REPORTS ON WELL SANTA FE  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER-

2. Name of Operator  
THE DESANA CORPORATION

3. Address of Operator  
600 Building of the Southwest, Midland, Texas 79701

4. Location of Well  
UNIT LETTER M, 660 FEET FROM THE South LINE AND 660 FEET FROM  
THE West LINE, SECTION 36 TOWNSHIP 5-N RANGE 30-E NMPM.

7. Unit Agreement Name

8. Farm or Lease Name  
Wichita State

9. Well No.  
1

10. Field and Pool, or Wildcat  
Wildcat

15. Elevation (Show whether DF, RT, GR, etc.)  
DF 4618', RT 4619', GL 4602'

12. County  
Quay

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> Plug Back

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1-13-83: TD 7150' Plug back as follows: Set 50 sx Class "C" @ 6400', set 100 sx Class "C" @ 4700', set 120 sx @ 3400', set 50 sx Class "C" w/3% CaCl @ 2585'. Tag top of plug @ 2460'.

1-14-83: Drilled out plug to 2520' (hard cmt). Set 35 sx plug Class "C" w/3% CaCl from 2520', reverse cmt out from 2448', reverse total 10 sx to pit. Tagged cmt @ 2465'.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Tom R. Corp TITLE Production Superintendent DATE 1-20-83

APPROVED BY Carl Kling TITLE DISTRICT SUPERVISOR DATE 1/24/83

CONDITIONS OF APPROVAL, IF ANY: