ENERGY AND MINERALS DEPARTM	IENT	
NO. OF COPIES ACCEIVED	OIL CONSERVATION DIVISION	
DISTRIBUTION	P. O. BOX 2088	Form C-103
SANTA FE	SANTA FE, NEW MEXICO 87501	Revised 10-1-78
FILE		
U.S.G.S.		Sa. Indicate Type of Lease
LAND OFFICE		State Fee X
OPERATOR]	5. State Oil & Gas Lease No.
(DO HOT USE THIS FORM FOR DE	RY NOTICES AND REPORTS ON WELLS OPOSALS TO DAILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. TON POR PERMIT	
1.	CONTRACTOR, FOR SUCH PROPOSALS.)	7. Unit Agreement Nome
OIL GAB WELL X	OTHER-	. Our Adreement Nome
2. Name of Operator Vatos Potroloum Com	8. Farm or Lease Name	
Yates Petroleum Corpo	T-4 Cattle Co.	
3. Address of Operator 207 South 4th St., Ar	9. Well No.	
4. Location of Well	2	
		10. Field and Pool, or Wildcat
UNIT LETTER N	Und. Penn	
THEWEST LINE, SECTI	ION 32 TOWNSHIP 11N RANGE 27E NMP	<u>ν.</u> ΑΠΠΠΠΠΠΠΠΠΠ
mmmmmm		
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
$\frac{16}{10000000000000000000000000000000000$	4330.2' GR	Ouav
Check	Appropriate Box To Indicate Nature of Notice, Report or O	ther Data
NOTICE OF I	NT REPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB	The same approximent
	OTHER Well Status	X
OTHER	[_]	
17. Describe Proposed or Completed Op	perations (Clearly state all pertinent details, and give pertinent datas, including	

17. Describe Proposed of Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.
TD. 70001

TD 7033'. Moved in and rigged up. Released packer. Displaced 5-1/2" casing w/14 bbls of 2% KCL water, POOH w/packer. Strap tubing out of hole. Ran 5-1/2" CIBP set 5320'. WIH w/packer on tubing set 5271'. Swab well down to 4700'. Perforated w/1" and 9/16" gun from 5299-5302' w/12 holes (4 SPF). Went on vacuum after perf. Ran swab to 5263, no fluid. Treated perfs 5299-5303' w/750 gal 3% HCL acid. Released packer, POOH 6 joints. Reset packer 5111'. Swab well down to 5103'. Prep to Plug and Abandon.

18. I hereby certify that the information above is true and complete to the beat of my knowledge and belief.

encofrigante Boodbit	Production Supervisor	DATE 5-17-84
Rr. Elphann	elt APD eac margaren .	= 22 414
CONDITIONS OF APPROVAL, IF ANY:	TITLE	DATE