

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	<input checked="" type="checkbox"/>
U.S.G.P.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease  
State ☐ Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☐ GAS WELL ☐ OTHER ☒ P&A

Name of Operator  
Yates Petroleum Corporation

Address of Operator  
207 South 4th St., Artesia, NM 88210

Location of Well

UNIT LETTER H 1980 FEET FROM THE North LINE AND 660 FEET FROM  
THE East LINE, SECTION 31 TOWNSHIP 11N RANGE 27E NMPM.

7. Unit Agreement Name

8. Farm or Lease Name

T-4 Cattle Co.

9. Well No.

3

10. Field and Pool, or Wildcat  
Undesignated

11. Elevation (Show whether DF, RT, GR, etc.)

4367' GR

12. County

Quay

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☐  
FULL OR ALTER CASING ☐

PLUG AND ABANDON ☒  
CHANGE PLANS ☐

REMEDIAL WORK ☐  
COMMENCE DRILLING OPNS. ☐  
CASING TEST AND CEMENT JOB ☐

ALTERING CASING ☐  
PLUG AND ABANDONMENT ☐

OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 4973'. Propose to plug and abandon well as follows:

- 1) Set CIPB at approx. 4160' and cap w/10 sx cement.
- 2) Cut and pull 5½" casing from 2880'.
- 3) GIH w/tubing and spot cement plug from 3100' (66' below 9-5/8" casing shoe) up to 50' above 5½" casing stub. Tag this plug after setting.
- 4) Set cement plug inside 9-5/8" casing from 1900-2100'.
- 5) Set cement plug inside 9-5/8" casing from 325-425'.
- 6) Pump cement down 13-3/8" x 9-5/8" casing annulus (estimate 100 sx.).
- 7) Install surface plug and regulation abandonment marker.

Note: If landowner elects to take over well, it will be turned over to him after setting and tagging plug at 3100' (described in item 3 above).

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature]

TITLE Production Supervisor

DATE 6-18-84

APPROVED BY [Signature]  
CONDITIONS OF APPROVAL, IF ANY:

TITLE OIL AND GAS INSPECTOR

DATE 6-19-84

