CONDITIONS OF APPROVAL, IF ANY:

## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

District Office	
DISTRICT I P.O. Box 1980, Hobbs, NM 88240 OIL CONSERVATION DIVISION P.O.Box 2088	WELL API NO.
DISTRICT II P.O. Drawer DD, Artesia, NM 88210 Santa Fe, New Mexico 87504-2088	30-037-20038
	5. Indicate Type of Lease  STATE FEE
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name BRAVO DOME CO2 GAS UNIT
1. Type of Well	-
OIL GAS OTHER CO2	
2. Name of Operator	8. Well No.
Amoco Production Company	1735-121G
3. Address of operator	9. Pool name or Wildcat
P.O. Box 606, CLAYTON, NEW MEXICO 88415  4. Well Location	BRAVO DOME CO2 GAS UNIT
	650 Feet From The EAST Line
Section 12 Township 17N Range 35E	N7(D) (
Section 12 Township 17N Range 35E  10. Elevation (Show whether DF, RKB, RT, GR, etc.)	NMPM QUAY County
4573	
RFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
EMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING  JLL OR ALTER CASING CASING TEST AND CE  THER: OTHER: YEAR  2. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, work.) SEE RULE 1103.	OPNS. PLUG AND ABANDONMENT EMENT JOB
COMMENCE DRILLING  CASING TEST AND CE  CHER:  OTHER:  YEAR  2. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, work.) SEE RULE 1103.  YEAR MONTH/DAY TUBING PRESSURE CASING PRESSURE BLEED DOWN TIME 1990 JUNE 21 380# 0	OPNS. PLUG AND ABANDONMENT [ MENT JOB  RLY BRADENHEAD TEST (TA WELL)
COMMENCE DRILLING  CASING TEST AND CE  OTHER: YEAR  C. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, work.) SEE RULE 1103.  YEAR MONTH/DAY TUBING PRESSURE CASING PRESSURE BLEED DOWN TIME 1990 JUNE 21 380# 0 1991 JUNE 11 380# 0	OPNS. PLUG AND ABANDONMENT [ EMENT JOB [  RLY BRADENHEAD TEST (TA WELL)
EMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING  JLL OR ALTER CASING CASING TEST AND CE  THER: OTHER: YEAR  2. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, work.) SEE RULE 1103.  YEAR MONTH/DAY TUBING PRESSURE CASING PRESSURE BLEED DOWN TIME 1990 JUNE 21 380# 0 1991 JUNE 11 380# 0 1992 JUNE 11 370# 0	OPNS. PLUG AND ABANDONMENT ( EMENT JOB ( ELY BRADENHEAD TEST (TA WELL)
COMMENCE DRILLING  CASING TEST AND CE  THER:  Check the proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, work.) SEE RULE 1103.  YEAR MONTH/DAY TUBING PRESSURE CASING PRESSURE BLEED DOWN TIME  1990 JUNE 21 380# 0  1991 JUNE 11 380# 0  1992 JUNE 11 370# 0  1993 MAY 17 380# 0  1994 MAY 26 375# 0  1996  1997  1998  1999	OPNS. PLUG AND ABANDONMENT [ EMENT JOB [  RLY BRADENHEAD TEST (TA WELL)
EMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING  JLL OR ALTER CASING CASING TEST AND CE  THER: OTHER: YEAR  2. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, work.) SEE RULE 1103.  YEAR MONTH/DAY TUBING PRESSURE CASING PRESSURE BLEED DOWN TIME  1990 JUNE 21 380# 0  1991 JUNE 11 380# 0  1992 JUNE 11 370# 0  1993 MAY 17 380# 0	OPNS. PLUG AND ABANDONMENT MENT JOB CLY BRADENHEAD TEST (TA WELL)  including estimated date of starting any proposed