

**RECEIVED**  
AUG 20 1973  
NEW MEXICO OIL CONSERVATION COMMISSION  
OIL CONSERVATION COMM  
Santa Fe

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

**SUNDRY NOTICES AND REPORTS ON WELLS**

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry hole	7. Unit Agreement Name
2. Name of Operator Zetco Petroleum Co., Inc. (Formerly - Puretex Oil Co.)	8. Farm or Lease Name Frank Chappell, Jr.
3. Address of Operator 357 Lulu Street, Wichita, Kansas 67211	9. Well No. 1
4. Location of Well UNIT LETTER _____, 548 FEET FROM THE East LINE AND 1020 FEET FROM THE South, LINE, SECTION 13 TOWNSHIP 12 N RANGE 29 E NMPM.	10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 4081 Gr.	12. County San Miguel

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This subsequent report to our C-103 of June 29, 1973 is to amend the plugging procedure as per telephone conversation with the inspector, Mr. J. E. Kapteina, August 10, 1973.

Plugging and abandoning procedure will now be as follows; leave all of the pipe in the hole, set cement plug from TD 4932' to 4800' bridge hole at 150' and fill to the surface with cement, tie surface casing and long string together w/cement in the annulus, set regulation marker and clear location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Agent DATE 8-15-73

APPROVED BY [Signature] TITLE Oil & Gas Inspector DATE 8/20/73

CONDITIONS OF APPROVAL, IF ANY: