

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

3a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator Tom L. Ingram		8. Farm or Lease Name Gihon "31"
3. Address of Operator P. O. Box 1757, Roswell, N. M. 88202		9. Well No. 1
4. Location of Well UNIT LETTER <u>G</u> <u>2970</u> FEET FROM THE <u>South</u> LINE AND <u>51814</u> FEET FROM THE <u>East</u> LINE, SECTION <u>31</u> TOWNSHIP <u>13-N</u> RANGE <u>30-E</u> NMPM.		10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 4028 GR		12. County San Miguel

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Purpose to plug and abandon as follows:

25 sx @ 4411  
25 sx @ 3625  
25 sx @ 3050  
25 sx @2415 - 2515  
25 sx @ 1900 - 2000  
25 sx @ 990 - 1090  
15 sx bullheaded between 8 5/8 and 5 1/2  
10 sx @ 448  
10 sx @ surface

Mud laden brine to be used between plugs.

Dry hole marker to be set at surface.

2 Copies of Compensated Neutron Log are enclosed.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Tom L. Ingram</u>	TITLE <u>Operator</u>	DATE <u>9-8-88</u>
APPROVED BY <u>[Signature]</u>	TITLE <u>DISPATCH SUPERVISOR</u>	DATE <u>9-19-88</u>
CONDITIONS OF APPROVAL, IF ANY:		