OIL CONSERVATION DIVISION P. O. BOX 2088  SANTA FE SANTA FE, NEW MEXICO 87501  JUL 13		form C-103 Revised 10-1-
U.S.G.S.  LAND OFFICE  OFERATOR  OFERATOR  OFERATOR	Signal DAVISION	
SUNDRY NOTICES AND REPORTS ON WELLS  100 HOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  100 HOT USE "APPLICATION FOR PERMIT _" IFORM C-101) FOR SUCH PROPOSALS.	7. Unii Agreemen	
I. OIL X CAS OTHER-	8. Farm or Lease	
Pelto Oil Company	Ortiz	
1. Address of Operator Two Greenspoint Plaza, Suite 400 16825 Northchase, Houston, Texas 77060	9. Well No.	
4. Location of Well  West Line and 4290 FEET FROM THE West LINE AND 4290 FEET FROM	10. Field and Po	
THE North LINE, SECTION 26 TOWNSHIP 14N RANGE 8E HMPM.		
15. Elevation (Show whether DF, RT, GR, etc.)  KB 5804	12. County Santa Fe	
Check Appropriate Box To Indicate Nature of Notice, Report or Ott NOTICE OF INTENTION TO:  SUBSEQUENT	her Data r report of:	
PERFORM REMEDIAL WORK PLUE AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON COMMENCE DRILLING OPNS.		NG EASING
PULL CR ALTER CASING CHANGE PLANS CASING TEST AND CEMENT JOB		Г
.HCR		
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1103.	estimated date of s	tarting any propose
Moved in and rigged up Farmington well service unit 6-1 Perforated Dakota "A" 7205-12, 7216-20, 7232-58, Acidi 5000 gallons 15% HCL, Swab tested, perforate additional 7205\(\frac{1}{2}\)-12\(\frac{1}{2}\), 7216\(\frac{1}{2}\)-20\(\frac{1}{2}\), 7231\(\frac{1}{2}\)-57\(\frac{1}{2}\). Halliburton frac Dako zone with 4000 gallons 15% HCL, 80,000 gallons 40\(\pi\) cros gel and 67,000\(\pi\) 20/40 sand. Swab tested on 7-6-81,swab hours, recovered 13 BO, 34 BLW, well swabbed dry. Left CIBP at 7356. Plug malfunctioned. Set Halliburton CIB and press tested to 1500\(\pi\) for 30 minutes, Dresser ran d and dumped 3.5 sacks cement (1.18cubic foot per sack) o CIBP, second run dump bailer hit top of liner at 6726 sacks cement, ran bit and scraper to 7140 and hit cemen out of hole with bit and scraper. Now preparing to per and test Greenhorn formation from 7003-7075.	zed with holes ta "A" s link bed 11 Halliburt P at 7175 ump bailer n top of lost 3.5 t. Pulled forate	
Pelto Oil Company respectively request that all informa held confidential. Please hold information confidential for one year as fur evaluation is anticipated on Dakota A zone.  Logs to be hand delivered by 7-15-81		
If vereby certify that the information above is true and complete to the best of my knowledge and belief.	• .	
Petroleum Consultant	DATE 1-1	0-81
	7 .	5-81