OIL CONSERVATION COMMISSION P. O. BOX 871 SANTA FE, NEW MEXICO

INSPECTION REPORT July 10, 1952

LUBBOCK MACHINE COMPANY, INC.

Re: H. B. Colbough, #1 SUSU Sec. 12-10-12E Torrance County

This well has reached a total depth of 996^t and the formation here is a ro-worked granite wash. Today I found the well shut down because of a bad clutch on the drilling motor. Pending receipt of the repaired clutch and mounting of same, drilling should be resumed by Saturday.

On July 3, 7" O. D. Casing was landed at 933' for an apparantly good water shut-off. After drilling was resumed a void of about one foot in depth was hit right under the pipe shoe and water came in again. This water is now standing in the hole from 400 to 450'. The hole can be baled down but not dry. This 7" will either be under dug and lowered to a good water tight seat or else pulled and the hole deepened to an impervious stratum for en effective water shut-off.

5.4.C.

Eugene A. Chavez, Geological Scout - District 4

jh