STATE OF NEW MEXICO OFFICE OF STATE GEOLOGIST SANTA FE, NEW MEXICO

1 July 1948

Mr. F. B. Umbarger P. O. Box 34 Encino, New Mexico

Dear Sir:

It has come to our attention that your #1 State which is listed on your bond and form C-101 as located 330 feet north of the south line and 330 feet west of the east line of Sec. 3, T8N-R14E is not being drilled on the location given. Several oil scouts have reported the location as 660 feet from the south and 1760 feet from the west line.

If this is true, I would appreciate your correcting the location with this office as soon as possible. You can not legally drill a location that does not correspond with the location given on your bond and C-101.

Sincerely yours,

FRANK C. BARNES Ceologist

FCB:bsp

cc: H. Sweeney