

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
LG-1987-2	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Carbon Dioxide and Hydrocarbons		7. Unit Agreement Name
2. Name of Operator		8. Farm or Lease Name
HNG FOSSIL FUELS COMPANY		EXCEL
3. Address of Operator		9. Well No.
P. O. Box 1188, Houston, Texas - 77001		3
4. Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER <u>M</u> <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>20</u> TOWNSHIP <u>29N</u> RANGE <u>33E</u> NMPM.		Wildcat
15. Elevation (Show whether DF, RT, GR, etc.)		12. County
GR=5560'		Union

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <u>Approval pending.</u> <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>	OTHER <u>See below</u> <input type="checkbox"/>

RULE 201. NOTICE

Notice of intention to plug must be filed with the Division by the owner or his agent prior to the commencement of plugging operations on Form C-103, Sundry Notices and Reports on Wells, which notice shall state the name and location of the well and the name of the operator. In the case of a newly completed dry hole, the operator may commence plugging by securing the approval of the Division as to the method of plugging and the time plugging operations are to begin. He shall, however, file the regular notification form.

RULE 202. PLUGGING AND ABANDONMENT

A. PLUGGING

Before any well is abandoned, it shall be plugged in a manner which will permanently confine all oil, gas, and water in the separate strata originally containing them. This operation shall be accomplished by the use of mud-laden fluid, cement and plugs, used singly or in combination as may be approved by the Division. The exact location of abandoned wells shall be shown by a steel marker at least four inches in diameter set in concrete, and extending at least four feet above mean ground level. The name and number of the well and its location (unit letter, section, township, and range) shall be welded, stamped, or otherwise permanently engraved into the metal of the marker. Seismic, core or other exploratory holes drilled to or below sands containing fresh water shall be plugged and abandoned in accordance with the applicable provisions recited above. Permanent markers are not required on seismic holes.

Within thirty days following the completion of plugging operations on any well, a record of the work done shall be filed with the Division in TRIPLICATE, on Form C-103. Such report shall be filed by the owner of the well and shall include the date the plugging operations were begun along with the date the work was completed; a detailed account of the manner in which the work was performed; the depths and lengths of the various plugs set; the nature and quantities of materials employed in plugging operations; the amount, size and depth of all casing left in the hole and the weight of mud employed in plugging the well and any other pertinent information. No plugging report submitted on Form C-103 shall be approved by the Division unless such report specifically states that pits have been filled and the location levelled and cleared of junk. The filing of Form C-105, Well Completion or Recompletion Report and Log is also necessary to obtain Division approval of a plugging report.

It shall be the responsibility of the owner of the plugged well to contact the appropriate District Office of the Division to arrange for an inspection of the plugged well and the location by a Division representative.

no logs

Level?

clean?