

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO. 30-059-20052
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name BOCDGU-1934
8. Well No. 051
9. Pool name or Wildcat Tubb
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4915' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER C02
2. Name of Operator Amoco Production Company
3. Address of Operator PO Box 606, Clayton, NM 88415
4. Well Location Unit Letter J : 1980 Feet From The South Line and 1969 Feet From The East Line Section 5 Township 19N Range 34E NMPM Union County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Install Casing Liner <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- | | |
|---|--|
| 1934-051J | 10. FLOW WELL UP CSG 16 DAYS |
| 1. MIRUSU 3/7/97 | 11. MIRUSU 3/24/97 |
| 2. NU BOP | 12. RUN TBG, PKR, ON/OFF TOOL, SUB |
| 3. KILL WELL | 13. TLA 2279', PSA 2275' |
| 4. LAY DOWN 3 1/2 FG TBG, PKR, TAILPIPE | 14. NDBOP |
| 5. RDMOSU 3/8/97 | 15. INSTALL TBG HANGER |
| 6. RUN POLYBORE GAUGE RING TO 1513' | 16. PRESSURE TST PKR & CSG TO 500 PSI - OK |
| 7. UNABLE TO GET PAST 1513' | 17. RDMOSU 3/25/97 |
| 8. PULL GAUGE RING | 18. RETURN WELL TO PRODUCTION 3/25/97 |
| 9. RETURN WELL TO PRODUCTION 3/12/97 | |

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Billy E. Prichard TITLE Field Foreman DATE 3/27/97

TYPE OR PRINT NAME Billy E Prichard TELEPHONE NO. 374-3053

(This space for State Use)

APPROVED BY Ry E. Prichard DISTRICT SUPERVISOR DATE 4/18/97

CONDITIONS OF APPROVAL, IF ANY