DISTRICT I P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION 2040 Pacheco St.

WELL API NO.	
	30-059-20064

DISTRICT II P.O. Drawer DD, Artesia, NM 88	210·
DISTRICT III	<b>9741</b>

NM 87505 Santa Fe,

Indicate Type of Lease		
STATE	FEE	LX.

P.O. Drawer DD, Ariesia, NM 88210	<u> </u>	5. Indicate Type of Lease
DISTRICT III		STATE FEE X
1000 Rio Brazos Rd., Aztec, NM 87410	•	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON	WELLS	
( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DE	EPEN OR PLUG BACK TO A	
DIFFERENT RESERVOIR. USE "APPLICATION FO	R PERMIT"	7. Lease Name or Unit Agreement Name
(FORM C-101) FOR SUCH PROPOSALS.	)	
1. Type of Well: OIL GAS		
WELL WELL OTHER (	202	BDCDGU-1935
2. Name of Operator		8. Well No.
Amoco Production Company	•	061
3. Address of Operator		9. Pool name or Wildcat
PO Box 606, Clayton, NM 88415		Tubb
4. Well Location		
Unit Letter G: 2044 Feet From The North	1980 Line and	Feet From The Line
		Feet From The Line
Section 6 Township 19N	Range 35E	Union NMPM County
10. Elevation (Show wh	ether DF, RKB, RT, GR, etc.)	NMPM County
//////// 4690	GR	<i>\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\</i>
11. Check Appropriate Box to Indic.	ate Nature of Notice De	Y District on Other Day
MOTIOE OF INTENTION TO		
NOTICE OF INTENTION TO:	SUBS	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON	DEMESTAL MOST	
FEGG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS [	COMMENCE DRILLING	OPNS. PLUG AND ABANDONMENT
DUIL OF ALTER CARING		
PULL OR ALTER CASING	CASING TEST AND CE	MENT JOB
OTHER: Install Casing Liner	OTHER:	
<ol> <li>Describe Proposed or Completed Operations (Clearly state all pertinent detail work) SEE RULE 1103.</li> </ol>	ls, and give persinent dates, includi	ing estimated date of starting any proposed
MIRUSU SNUB AND PO	LYBORE PROCEDURE	N EALTIN (EXT
RUN & SET 1.625 BLK PLG IN PROFILE NIP	NSTALL PRODUCTION RWTP UP 5.5 STEEL C	
BLEED DOWN TBG	PRODUCE FOR 12 TO	
NIPPLE UP BOP	MOVE IN RIG UP SER'	
REL ON/OFF TOOL	SHUT IN BOP-BLINDS	
SWAB & BLOW WELL DRY		NE ,SET INFLATTABLE BP
LAY DOWN FG TBG & ON/OFF TOOL OS	SET IBP ABOVE TOP I	PERF
RUN POLYBORE GAUGE RING TO PKR CHANGE RAMS IN BOP	BLEED CSG TO 0 PSI	NI ARG
RUN ON/OFF TOOLOS W/SW	RUN 9-31/8" DRILL CO RIG UP RRU	JLLARS
LATCH ON TO PKR W/WS	RUN POLYLINER TO I	MELATTADIE DD
RIG UP RIG ASSISTED SNUBBING UNIT		ING & PULL DRILL COLLARS
REL PKR	FUSE ON WELLHEAD	
SNUB TBG, PKR, TAILPIPE OUT OF WELL	INSTALL SS ADAPTER	
SHUT IN WELL W/BLIND RAMS	RETRIEVE IBP WITH V	
RIG DOWN SNUBBING UNIT	RWTP	
INSTALL SS WELLHEAD BONNET ON TOP OF BOP	RDMOSU	
hereby certify that the information above is true and complete to the best of my knowledge	and halief	
The state of the s		
SIONATURE BUlly E. Freehau	mue Field Forem	1an 5/29/97
. /		
TYPEORPRININAME Billy E Prichard		тецерноне ко, 374 – 3053
This space for State Use)		
(/ON /)		
1 ~ 3.11.17		<i>f j</i>

APPROVED BY THE CONDITIONS OF APPROVAL, IF ANY: