NO. OF COPIES RECEIVED			Form C-103	
DISTRIBUTION		The seal V and	Supersedes Old	
SANTA FE			C-102 and C-103	
FILE		SERVATION COMMISSION	Effective 1-1-65	
U.S.G.S.		la de la companya de	5a. Indicate Type of Lease	
LAND OFFICE		GIL CLE STATE SIC	State Fee X	
OPERATOR		SideTA FE	5. State Oil & Gas Lease No.	
(DO NOT USE THIS FORM FOR PUSE "APPLICA	RY NOTICES AND REPORTS ON ROPOSALS TO DRILL OR TO DEEPEN OR PLUG E ATION FOR PERMIT - " (FORM C-101) FOR SUC	WELLS BACK TO A DIFFERENT RESERVOIR. CH PROPOSALS.)		
11.	7. Unit Agreement Name			
	2 OTHER-			
2. Name of Operator	8. Farm or Lease Name			
Amoco Production Company			Hutcherson B	
3. Address of Operator	9. Well No.			
P. O. Box 68 Hobbs, NM 88240			20	
4. Location of Well			10 Field and Deel as Will i	
UNIT LETTER	Und. Tubb			
LASL LINE, SECT	18 TOWNSHIP	BANGE 34-E	$\boldsymbol{\nabla}$	
	<u> </u>			
15. Elevation (Show whether DF, RT, GR, etc.)			12. County	
4932 GL			Union	
Check	Appropriate Box To Indicate N	lature of Notice Report of Oth	her Data	
Check Appropriate Box To Indicate Nature of Notice, Report or Oth NOTICE OF INTENTION TO:			REPORT OF:	
SUBSEQUEN		REFORT OF:		
PERFORM REMEDIAL WORK	PLUG AND ABANDON X	REMEDIAL WORK	ALTERING CASING	
TEMPORARILY ABANDON		COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT	
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB	FEED AND ABANDONMENT []	
		OTHER		
OTHER				
	· · · · · · · · · · · · · · · · · · ·			
17. Describe Proposed or Completed O	operations (Clearly state all pertinent deta	ails, and give pertinent dates, including	estimated date of starting any proposed	

On 12-3-80 Moran Drilling Co. (Rig #56) spudded a 12-1/4" hole at 7:30 p.m. Drilled to a TD of 701' and ran 8-5/8" casing set at 701'. Cemented with 475 SX Class H cement. Plugged down at 6:00 a.m. 12-5-80. Circulated 75 SX. WOC 19 hrs. Tested casing with 800# for 30 min. Test OK. Reduced hole to 707/8" and resumed drilling. Drilled to a TD 1642 and lost circulation. Unable to regain circulation. Propose to P X A per the following procedure: Set Class H cement plug from 1250'-1000'. WOC 4 hrs. and tag plug. Set Class H cement plug 800'-600'. WOC 4 hrs. and tag plug. Set 20 SX surface plug.

0+2-NMOCD, SF	1-Hou	1-Susp	1-BD		
		and complete to the be	est of my knowledge and belief.		<u> </u>
_ ZOU N	airs		<u>Admin, Analyst</u>	DATE	1-13-81
		TITLE	Admin. Analvst	D + 7 F	1-13