·		
Submit 3 Copies	State of New Mexico Energy, Minerals, and Natural Resources Department	Form C-103
to Appropriate District Office	Energy, Minerals, and Natural Resources Department	Revised 1-1-89
	OIL CONSERVATION DIVISION	WELL API NO.
DISTRICTI		
P.O. Box 1980, Hobbs, NM 88240	P.O. Box 2088	30-059-20108
DISTRICT II	Santa Fe, New Mexico 87504-2088	5. Indicate Type of Lease
P.O. Drawer DD, Artesia, NM 88210		STATE FEE
DISTRICT III		6. State Oil & Gas Lease No.
1000 Rio Brazos Rd., Aztec. NM 87410		
SUNDRY	NOTICES AND REPORTS ON WELLS	
	R PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	
	ESERVOIR. USE "APPLICATION FOR PERMIT"	7. Lease Name or Unit Agreement Name
(FO	IRM C-101) FOR SUCH PROPOSALS.)	-
L. Type of Well		BRAVO DOME CO2 GAS UNIT
OIL GAS WELL WEL		
2. Name of Operator		8. Well No.
AMOCO PRODUCTION C	νομάρανα	2134-341K
3. Address of Operator		9. Pool name or Wildcat
P.O. Box 303, AMISTAI	D, NEW MEXICO 88410	BRAVO DOME CO2 GAS UNIT
4. Well Location		
Unit Letter K : 198	0 Feet From The South Line and 1980	Feet From The West Line
Section 34	Township 21N Range 34E NMI	PM Union County
	10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4810 GR	
Check Appropriate Box to Indicate Nature of Notice. Report, or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK PLUG AND ABANDON X REMEDIAL WORK ALTERING CASING		
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT		
PULL OR ALTER CASING		
OTHER:	OTHER:	
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.		
MIRUSU, kill well as necessary, NUBOP, release packer, lay down production tubing and packer, run workstring to 2,449		
feet, spot 71 sacks of cement, pull workstring. WOC, run workstring, tag cement, cement should be above 2,332 feet,		
pressure test casing to 500 psi, displace casing with mud laden fluid, pull workstring to 1,976 feet, spot 10 sacks of cement,		
pull workstring to 30 feet and fill casing with cement. NDBOP, cut off wellhead, install PXA marker, RDMOSU, cut off well		
anchors and clean location.		
L hereby certify that the information above is	true and complete to the pest of my knowledge and belief.	
$\left( \bigcap_{i} \right) = \left( \left( \bigcap_{i} \right) = \left( \bigcap_{i} \right) = \left( \bigcap_{i} \right) = \left( \left( \bigcap_{i} \right) \right) = \left( \left( \bigcap_{i} \right) = \left( \bigcap_{i} \left( \bigcap_{i} \right) = \left( \bigcap_{i} \right) = \left( \bigcap_{i} \left($		
SIGNATURE	CCCMUT TITLE Field Foreman	DATE 8-18-99
TYPE OR PRINT NAME Danny J Holcom		TELEPHONE NO (505) 374-3010
(This space for State Use) APPROVED BY	E offine DISTRICT SUPERV	ISOR DATE 8/23/99
CONDITIONS OF APPROVAL. IF ANY		
	v	