Submit 3 Copies to Appropriate	Energ	State of New y, Minerals, and Natu		Form C·103 Revised 1·1·89			
District Office		H CONCEDU					
DISTRICT I	OIL CONSERVATION DIVISION				PI NO.		
P.O. Box 1980, Hobbs, NM 88240		P.O. Bo	x 2088	3	0-059-20110		
DISTRICT II		Santa Fe, New Mexic	co 87504-2088	5. Indicate	Type of Lease		
P.O. Drawer DD, Artesia, NM 88210				S	TATE FEE	٦	
DISTRICT III				6. State O	il & Gas Lease No.	=	
1000 Río Brazos Rd., Aztec, NM 87410				0. 2.2.0	a C Gus Leuse 110.		
CHADD	V NOTICES AND	DEDODTE ON WELLE			5.00	Service T	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A							
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"					7. Lease Name or Unit Agreement Name		
	(FORM C-101) FOR S	JCH PROPOSALS.)			~		
1. Type of Well				BRAVO D	DOME CO2 GAS UNIT		
ON WELL	GAS WELL	OTHER	CO2				
2. Name of Operator		Other		8. Well No			
_	DANIV			o. Well No			
AMOCO PRODUCTION COMPANY					2035-181F		
3 Address of Operator				9. Pool name or Wildcat			
P.O. Box 303, AMISTAD,	NEW MEXICO	88410	· · · · · · · · · · · · · · · · · · ·	BRAVO D	OME CO2 GAS UNIT		
4. Well Location							
Unit Letter F	1980	Feet From The NOR	ΓΗ Line and 1980	Fee	et From The WEST Lin	.e	
Section 18		Township 20N	Range 35E	NMPM	UNION County		
		10 Elevation (Show	whether DF, RKB, RT, GR, etc.)				
		868 888 868 N	4667 <u>GL</u>				
C	seck Appro	printa Pay to India	cate Nature of Notice, I	Compart or Ot	la a Data	State L	
		priate box to mult	1	-			
NOTICE OF INTENTION TO: SUBSE				BSEQUENT REPOR	T OF:		
PERFORM REMEDIAL WORK	PLUG AND	ABANDON X	REMEDIAL WORK		ALTERING CASING		
TEMPORARILY ABANDON	CHANGE PL	ANS 🗔	COMMENCE DRILLING OPNS.		PLUG AND ABANDONMENT	\vdash	
<u></u>]		SUMMERCE BRICERED OF IVO.		FEOD AND ABANDONMEN		
PULL OR ALTER CASING]		CASING TEST AND CEMENT JOB				
OTHER:			OTHER:				
12 Describe Proposed or Completed Opera SEE RULE 1103.	ations	(Clearly state all pertinent details, a	nd give pertinent dates, including estimated dat	e of starting any proposed	work)		
	cessary NII	IROP Pal nkr I D nr	oduction tbg and packer,R				
			tag cmt, Cmt_should be a				
			fluid, Pull tbg to 1858 ft,S				
Pull that o 30 ft and fill	csa with ce	ment NDBOP Cut	off wellhead, Install PXA	pot 15 sx cilit, marker PD	,		
MOSU, Cut off SU anch	nors and cle	an location	on wennead, matan 1 704 i	marker, ND			
in ear, ear an ea and	iore and ore	an roodhon					
						İ	
Ì		\bigcirc					
hereby certify that the information above is true	and complete to the he	est of my knowledge and helief					
IGNATURE /24	1 3 12	Tuline TITLE	Operations Specialist		DUT INODO		
			operations specialist		DATE 1/20/98		
YPE OR PRINT NAME B. E. Prichard This space for State Use)	SP/) /	/	And the state of t	21.7	TELEPHONE NO. (505) 374-3053	_	
PPROVED BY	- Dhi	UTTE TITLE	DISTRICT SUPER		DATE 2-5-98		
CONDITIONS OF APPROVAL, IF ANY:							