

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

# OIL CONSERVATION DIVISION

2040 Pacheco St.  
Santa Fe, NM 87505

WELL API NO.	20132
30-059	<del>20097</del>
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	

<p><b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)</p>	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER CO2	7. Lease Name or Unit Agreement Name BDCOGU-2034
2. Name of Operator Amoco Production Company	8. Well No. 101 X
3. Address of Operator PO Box 606, Clayton, NM 88415	9. Pool name or Wildcat Tubb
4. Well Location Unit Letter J : 1980 Feet From The South Line and 2080 Feet From The North Line Section 10 Township 20N Range 34E NMPM Union County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4810.6R	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: Install casing liner ☒

## SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

## SNUB AND POLYBORE PROCEDURE

MIRUSU  
RUN & SET 1.625 BLK PLG IN PROFILE NIP  
BLEED DOWN TBG  
NIPPLE UP BOP  
REL ON/OFF TOOL  
SWAB & BLOW WELL DRY  
LAY DOWN FG TBG & ON/OFF TOOL OS  
RUN POLYBORE GAUGE RING TO PKR  
CHANGE RAMS IN BOP  
RUN ON/OFF TOOL OS W/SW  
LATCH ON TO PKR W/SW  
RIG UP RIG ASSISTED SNUBBING UNIT  
REL PKR  
SNUB TBG, PKR, TAILPIPE OUT OF WELL  
SHUT IN WELL W/BLIND RAMS  
RIG DOWN SNUBBING UNIT  
INSTALL SS WELLHEAD BONNET ON TOP OF BOP

INSTALL PRODUCTION EQUIPMENT  
RWTP UP 5.5 STEEL CSG  
PRODUCE FOR 12 TO 20 DAYS  
MOVE IN RIG UP SERVICE UNIT  
SHUT IN BOP-BLINDS  
RUN BAKER WIRE LINE, SET INFLATTABLE BP  
SET IBP ABOVE TOP PERF  
BLEED CSG TO 0 PSI  
RUN 9-31/8" DRILL COLLARS  
RIG UP RRU  
RUN POLYLINER TO INFLATTABLE BP  
RUN 23/8" WORK STRING & PULL DRILL COLLARS  
FUSE ON WELLHEAD FLANGE  
INSTALL SS ADAPTER  
RETRIEVE IBP WITH WIRELINE  
RWTP  
RDMOSU

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Billy E. Prichard TITLE Field Foreman DATE 4/18/97  
TYPE OR PRINT NAME Billy E Prichard TELEPHONE NO. 374-3053

(This space for State Use)

APPROVED BY Ry E. Johnson TITLE DISTRICT SUPERVISOR DATE 6/2/97  
CONDITIONS OF APPROVAL, IF ANY: