Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

Daum Ci	OW CONCEDENT WY		
DISTRICT I P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVATIO		WELL API NO.
DISTRICT II	Santa Fe, N	M 87505	30-059-20141
P.O. Drawer DD, Artesia, NM 88210 DISTRICT III			5. Indicate Type of Lease STATE FEE FEE
1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease No.
(DO NOT USE THIS FORM FOR PROF DIFFERENT RESERV	ES AND REPORTS ON WEI POSALS TO DRILL OR TO DEEPEN POIR. USE "APPLICATION FOR PE 01) FOR SUCH PROPOSALS.)	OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
1. Type of Well: OIL GAS WELL WELL	ouriex COS		BDCDGU-2034
2. Name of Operator			8. Well No.
Amoco Production (Company	·	201
3. Address of Operator			9. Pool name or Wildcat
PO Box 606, Clayto	in, NM 88415		Tubb
Unit Letter G: 198	OFeet From The North	Line and198	BO Feet From The East Line
Section 20	Township 20N Ra	unge 345	NMPM Union County
	10. Elevation (Show whether 4877 to	· ·	
Charle As	/////	· · · · · · · · · · · · · · · · · · ·	Service Other Date
NOTICE OF INTE	opropriate Box to Indicate 1		SEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON		
		REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	
PULL OR ALTER CASING		CASING TEST AND CE	MENT JOB
OTHER: Install Casing	Liner X	OTHER:	
12. Describe Proposed or Completed Operation work) SEE RULE 1103.	is (Clearly state all pertinent details, an	d give pertinent dates, includ	ling estimated date of starting any proposed
MIRUSU RUN & SET 1.625 BLK PLA BLEED DOWN TBG NIPPLE UP BOP REL ON/OFF TOOL SWAB & BLOW WELL DE LAY DOWN FG TBG & ON RUN POLYBORE GAUGE CHANGE RAMS IN BOP RUN ON/OFF TOOLOS WA LATCH ON TO PKR WAWS RIG UP RIG ASSISTED SN REL PKR SNUB TBG, PKR, TAILPIP SHUT IN WELL WABLIND RIG DOWN SNUBBING UN INSTALL SS WELLHEAD	RY N/OFF TOOL OS RING TO PKR /SW S CUBBING UNIT E OUT OF WELL RAMS NIT BONNET ON TOP OF BOP	NSTALL PRODUCTIO RWTP UP 5.5 STEEL C PRODUCE FOR 12 TO MOVE IN RIG UP SER SHUT IN BOP-BLINDS RUN BAKER WIRE LII SET IBP ABOVE TOP I BLEED CSG TO 0 PSI RUN 9-31/8" DRILL CO RIG UP RRU RUN POLYLINER TO I RUN 23/8" WORK STR FUSE ON WELLHEAD INSTALL SS ADAPTEI RETRIEVE IBP WITH I RWTP RDMOSU	SSG 20 DAYS VICE UNIT S NE ,SET INFLATTABLE BP PERF DLLARS INFLATTABLE BP ING & PULL DRILL COLLARS FLANGE R
I hereby certify that the information above is true and			
SIGNATURE / / / / /	- I ruluu m	z Field Forema	DATE 2/27/97
TYPE OR PRINT NAME BILLY E F	richard		ТЕЦ ЕР НОНЕ NO. 374-3053
(This space for State Use)	7	DISTRICT SU	PERVISOR 3/17/87
APPROVED BY	тпи	E	DATE
CONDITIONS OF APPROVAL, IF ANY			