

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	☒
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-7

5a. Indicate Type of Lease	
State ☐	Fee ☐
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE APPLICATION FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☐ GAS WELL ☒ CO2 OTHER-		7. Unit Agreement Name BDCDGU
2. Name of Operator Amoco Production Company 505-374-8396 8384		8. Farm or Lease Name BDCDGU 2231
3. Address of Operator P. O. Box 68, Hobbs, New Mexico 88240		9. Well No. 161
4. Location of Well UNIT LETTER G 1650 FEET FROM THE North of Section 1650 THE East LINE, SECTION 16 TOWNSHIP 22-N RANGE 31-E N.M.P.M.		10. Field and Pool, or Wildcat Und. Tubb
15. Elevation (Show whether OF, RT, GR, etc.) 5055' GL		12. County Union

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER Plug and abandon ☐	CASING TEST AND CEMENT JOBS ☐	
		OTHER ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to plug and abandon subject well per the following method:

Run in hole with tubing and spot plugs as follows: (Note: Spot heavy mud between plugs containing 25 lbs. of gel per bbl of 10# brine). (a) Spot 25 sacks class H cement across top of Yeso and Glorietta (approx. 1690'-1500'); (b) Spot 100' cement plug across top of San Andres (1310'-1410'); (c) Spot 25 sacks class H cement across 8-5/8" casing shoe (approx. 600'-790'); and (d) Spot 10 sacks class H cement plug at surface. Weld on cap. Erect abandonment marker. Fill pits, level location, and clear area of junk.

0+2-NMOCD,SF 1-HOU 1-SUSP 1-CLF 1-Amerada 1-UGI 1-Cities Serv. 1-Conoco
1-CO2 in Action 1-Excelsior 1-Sun. Tex.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Cathy L. Forman TITLE Assist. Admin. Analyst DATE 8-3-82
APPROVED BY Carl Woody TITLE DISTRICT SUPERVISOR DATE 8-5-82
CONDITIONS OF APPROVAL, IF ANY: