

3/30/33

Memo

From

CARL ULVOG

Chief Geologist

To File C-16-26N-36E

Call from Dowell - Amarillo
Jim Aylor 806-435-5436
for plugging program.

I said, before prescribing where
plugs need to be set, I would
need a set of logs. Otherwise
hole must be cemented from
T. D. up into base of surface esp.
I estimated that (if logs are
available) I would require at
least 5 or 6 plugs.

They (Dowell) will try to get
logs sent here.