Submit 3 Copies		of New Mexico	Form C-103
to Appropriate	Energy, Minerals, an	d Natural Resources Department	Revised 1-1-89
District Office			
DISTRICT I	OIL CONSE	RVATION DIVISION	WELL API NO.
P.O. Box 1980, Hobbs, NM 88240	1	P.O. Box 2088	30-059-20366
DISTRICT II	Santa Fa Na	v Mexico 87504-2088	
P.O. Drawer DD, Artesia, NM 88210		4 MEXICO 8/304-2088	5. Indicate Type of Lease STATE FEE X
	•		STATE FEE X
DISTRICT III			6. State Oil & Gas Lease No.
1000 Rio Brazos Rd., Aztec, NM 874	410		
SUN	IDRY NOTICES AND REPORTS ON V	/ELLS	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"			7. Lease Name or Unit Agreement Name
	(FORM C-101) FOR SUCH PROPOSALS.)		
1. Type of Well			BRAVO DOME CO2 GAS UNIT
OL WELL	GAS WELL O	THER CO2	
2. Name of Operator		002	
1	COMMINANIA		8. Well No.
AMOCO PRODUCTION (LUMITANT		1934-252K
3. Address of Operator			9. Pool name or Wildcat
P.O. Box 303, AMIST	AD, NEW MEXICO 88410		BRAVO DOME CO2 GAS UNIT
4. Well Location			
Unit Letter K	: 2397 Feet From The	South Line and 140	77 Feet From The West Line
Section 25	Township 1	9N Range 34E	The state of the s
			NMPM Union County
	10. Elevation	(Show whether DF, RKB, RT, GR, etc.) 4732 GL	
11.	Check Appropriate Box to	Indicate Nature of Notice,	Report, or Other Data
	OF INTENTION TO:	1	BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	-	DOCADENT NEI ONT OT.
The same of the sa	LOG WAD YEMADOM	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OPNS.	X PLUG AND ABANDONMENT
PULL OR ALTER CASING		CASING TEST AND CEMENT JO	
OTHER:			°
OTREK.		OTHER:	
12. Describe Proposed or Completed Operations (Clearly state all partinent datass, and give partinent datas, including estimated data of starting any proposed work)			
SEE KULE TIUS.			
5-13-98			
Move in rig up rotary tools. Spud at 11:15. Drill 12-1/4" hole to 743'. Run 17 jt. of 23# WC-55 casing. Set @ 743'.			
Cement with 285 sacks of Prem. Plus with 29.cc - 1/4# Flow Seal. Circulate 100 sacks to pit. Test 8-5/8" to 500 psi 10.			
Midcon Prem. Plus @ 11.2# with 39. cc 1/4# Flow Seal. Tail in with 75 sacks Midcon Prem. Plus @13.2# with 39. cc 1/4#			
Flow Seal. Bump plug @ 06:45 5/15/98. Circulate 85 sacks to pit. MORT, wait on service with			
		,	wall on service unit.
1 11	s true and complete to the beet of my knowledge and	belief.	
SIGNATURE	Notioner	TITLE Field Team Leader	DATE 5/15/98
TYPE OR PRINT NAME D. J. Hoi	comb		
(This space for State Use)	0.4 ()		TELEPHONE NO. (505) 374-3010
APPROVED BY	Sold.	The state of the s	25 7:12 25 55 - 1- 1
CONDITIONS OF APPROVAL, IF ANY:	a Turing	THE DISTRICT SUPER	DATE <u>5/22/98</u>
A STRUCTURE OF APPROVAL, IF ANT:	'		